



Commercial Vehicle Inspection Report

Decal Number: GH82713
Decal Expiry Date: 2026-Jan-31
Inspection Number: 21420386

031-1
Inspection Result:
PASS

FACILITY: ROJ TRUCK & TRAILER / S6382 INSP. TYPE: Complete INSP. START: 2025-Jul-09 03:35 PM PDT
INSPECTOR: SMITH, NATHAN RYAN / 200455 INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more INSP. COMPLETE: 2025-Jul-09 05:35 PM PDT
WORK ORDER #: 049485 INSP. REASON: Semi-annual

VEHICLE JUR: Alberta REGI: VIN: 1XKWD40X3JR994700
PLATE #: UNIT/FLEET#: 1019 OWNER/LESSEE NAME: INTER-RAIL TRANSPORT LTD, INTER-RAIL TRANSPORT LTD
LICENCED GVW(kg): 63500 BODY STYLE: Truck ADDRESS: 1405 90 AVE NW, 1405 90 AVE NW
VEHICLE YEAR: 2018 ODOMETER: 913348 KM EDMONTON, Alberta
MAKE: KENWORTH HUB ODOMETER: T6P0C8, Canada
MODEL: CONSTRUCT BRAKE TYPE: Air
FUEL TYPE: Diesel

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Repaired (same day) #2 V-ROD FRONT BUSHINGS, RUBBER PUSHED OUT.
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) AIR FEEDING BACK INTO CHAMBER R#3 WITH BRAKES RELEASED.
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24L	Automatic	35	31
2	Clamp	30L	Automatic	40	35
3	Clamp	30L	Automatic	40	35

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
15			15	✓
16	16	16	16	
5	5	5	5	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	45	35
2	30	30
3	35	35

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	18	18
Lining (Shoe)	18	18
Lining (Shoe)	18	18

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Signature: Road Tester:

This Inspection Report was submitted to CVSE on 2025-Jul-09 05:37 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVP at the Commercial Vehicle Safety Enforcement.

CVSE0014

7/9/2025 5:38:03 PM PDT