



Commercial Vehicle Inspection Report

Decal Number: PY16997
Decal Expiry Date: 2026-Sep-30
Inspection Number: 21512505

503-1
Inspection Result:
PASS

FACILITY: NORTHERN B.C. TRUCKERS' / N5398
INSPECTOR: CHRISTIANSON, LESLIE RYAN / 106407
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2025-Sep-27 08:15 AM MST
INSP. COMPLETE: 2025-Sep-27 09:00 AM MST

WORK ORDER #:

VEHICLE JUR: British Columbia
PLATE #: 51455D
LICENSED GVW(kg): 999999
VEHICLE YEAR: 2010
MAKE: LODE KING
MODEL:
REGI: 10932230
UNIT/FLEET#: 48 end
BODY STYLE: Bulk Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2LDHG302XAF049894
OWNER/LESSEE NAME: Peace View hutterian brethren . .
ADDRESS: 4414 triangle rd
Dawson Creek, British Columbia
V1g0j4, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	37	38	16	15	15	15	
2	Clamp	30	Automatic	38	37	15	14	14	15	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	61	60
2	60	69

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	15	15.5
Lining (Shoe)	15	14.5

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Inspector: CHRISTIANSON, LESLIE RYAN

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Sep-27 11:37 AM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVP at the Commercial Vehicle Safety Enforcement.

CVSE0014

9/27/2025 11:37:57 AM MST