



Commercial Vehicle Inspection Report

Decal Number: PY16996
Decal Expiry Date: 2026-Sep-30
Inspection Number: 21512559

503-2
Inspection Result:
PASS

FACILITY: NORTHERN B.C. TRUCKERS' / N5398
INSPECTOR: CHRISTIANSON, LESLIE RYAN / 106407
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2025-Sep-27 09:00 AM MST
INSP. COMPLETE: 2025-Sep-27 09:43 AM MST

WORK ORDER #:

VEHICLE JUR: British Columbia
PLATE #: 51454D
REGI: 10932199
UNIT/FLEET#: 47ft
VIN: 2LDHG2839AF049893
OWNER/LESSEE NAME: Peace View hutterian brethren church ,
LICENCED GVW(kg): 999999
VEHICLE YEAR: 2010
MAKE: LODE KING
MODEL:
BODY STYLE: Bulk Trailer
ADDRESS: 4414 triangle rd
Dawson Creek, British Columbia
V1g0j4, Canada
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	35	38
2	Clamp	30	Automatic	39	40
3	Clamp	30	Automatic	33	36

Comment:

Tire Tread Depth (mm)

	Outer L	Inner L	Inner R	Outer R	Steering
	15	15	15	14	
	16	15	16	17	
	9	8	9	6	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	69	70
2	71	68
3	67	73

Comment:

Brake Lining/Pad (mm)

	Lining/Pad	Left	Right
	Lining (Shoe)	15	14.5
	Lining (Shoe)	15	15
	Lining (Shoe)	14	14

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

	Rotor/Drum	Left	Right
	Drum		
	Drum		
	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: CHRISTIANSON, LESLIE RYAN

Road Test Date:
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Sep-27 11:48 AM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VP at the Commercial Vehicle Safety Enforcement.

CVSE0014

9/27/2025 11:48:30 AM MST