

T08-4



# Commercial Vehicle Inspection Report

Decal Number: PY14950  
Decal Expiry Date: 2026-Feb-28  
Inspection Number: 21478590

Inspection Result:  
**PASS**

|                          |                                 |                      |                                                   |                           |                                |
|--------------------------|---------------------------------|----------------------|---------------------------------------------------|---------------------------|--------------------------------|
| <b>FACILITY:</b>         | NORTHERN B.C. TRUCKERS' / N5398 | <b>INSP. TYPE:</b>   | Complete                                          | <b>INSP. START:</b>       | 2025-Aug-29 11:05 AM MST       |
| <b>INSPECTOR:</b>        | COX, JAMES EDWARD / 110895      | <b>INSP. CLASS:</b>  | Class 2 - Heavy Vehicle with LGVW 5501 kg or more | <b>INSP. COMPLETE:</b>    | 2025-Aug-29 11:49 AM MST       |
| <b>WORK ORDER #:</b>     |                                 | <b>INSP. REASON:</b> | Semi-annual                                       |                           |                                |
| <b>VEHICLE JUR:</b>      | British Columbia                | <b>REGI:</b>         | 13559134                                          | <b>VIN:</b>               | 5KJRALD10LPLX3515              |
| <b>PLATE #:</b>          | SL8048                          | <b>UNIT/FLEET#:</b>  | 189                                               | <b>OWNER/LESSEE NAME:</b> | 4 EVERGREEN RESOURCES INC.     |
| <b>LICENCED GVW(kg):</b> | 63500                           | <b>BODY STYLE:</b>   | Logging Truck                                     | <b>ADDRESS:</b>           | BOX 189                        |
| <b>VEHICLE YEAR:</b>     | 2020                            | <b>ODOMETER:</b>     | 182924 KM                                         |                           | Moberly Lake, British Columbia |
| <b>MAKE:</b>             | WESTERN ST                      | <b>HUB ODOMETER:</b> |                                                   |                           | V0C1X0, Canada                 |
| <b>MODEL:</b>            |                                 | <b>BRAKE TYPE:</b>   | Air                                               |                           |                                |
|                          |                                 | <b>FUEL TYPE:</b>    |                                                   |                           |                                |

|                                                 |                                                                             |
|-------------------------------------------------|-----------------------------------------------------------------------------|
| Vehicle Identification (VIN)                    | Passed                                                                      |
| Section 1 - Power Train                         | Repaired (same day) Oil leaking from diff 2 oil filter, oil filter replaced |
| Section 2 - Suspension                          | Repaired (same day) Air leak at axle 2 right air bag fitting                |
| Section 3 - Brake System                        | Not Applicable                                                              |
| Section 3A - Air Brakes                         | Passed                                                                      |
| Section 3H - Hydraulic Brakes                   | Not Applicable                                                              |
| Section 4 - Steering                            | Passed                                                                      |
| Section 5 - Instruments and Auxiliary Equipment | Passed                                                                      |
| Section 6 - Lamps                               | Repaired (same day) Lic. Plate light                                        |
| Section 7 - Electrical System                   | Passed                                                                      |
| Section 8 - Frame and Body                      | Passed                                                                      |
| Section 9A - Tires                              | Passed                                                                      |
| Section 9B - Wheels                             | Passed                                                                      |
| Section 10 - Coupling Devices                   | Passed                                                                      |
| Section 11 - Other Vehicle Components           | Not Applicable                                                              |

## Air Brake Chamber Type, Size and Push Rod Stroke (mm)

| Axles | Type  | Size | Slack Adj. | Left | Right |
|-------|-------|------|------------|------|-------|
| 1     | Clamp | 24   | Automatic  | 29   | 27    |
| 2     | Clamp | 30   | Automatic  | 42   | 40    |
| 3     | Clamp | 30   | Automatic  | 36   | 40    |
| 4     | Clamp | 30   | Automatic  | 34   | 35    |

Comment:

## Tire Tread Depth (mm)

|   | Outer L | Inner L | Inner R | Outer R | Steering |
|---|---------|---------|---------|---------|----------|
| 1 | 17      |         |         | 17      | ✓        |
| 2 | 22      | 22      | 22      | 23      |          |
| 3 | 22      | 20      | 22      | 22      |          |
| 4 | 20      | 21      | 21      | 21      |          |

Comment:

## NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CV-SE0014

6/29/2025 1:20:57 PM MST



# Commercial Vehicle Inspection Report

Decal Number: PY14950  
Decal Expiry Date: 2026-Feb-28  
Inspection Number: 21478590

Inspection Result:  
**PASS**

## Air Brake Camshaft Rotation (degrees)

| Axles | Left | Right |
|-------|------|-------|
| 1     | 36   | 40    |
| 2     | 58   | 62    |
| 3     | 60   | 55    |
| 4     | 77   | 80    |

Comment:

## Brake Lining/Pad (mm)

| Lining/Pad    | Left | Right |
|---------------|------|-------|
| Lining (Shoe) | 18   | 18    |
| Lining (Shoe) | 16   | 16    |
| Lining (Shoe) | 16   | 16    |
| Lining (Shoe) | 14   | 13    |

Comment:

## Rotor Thickness or Drum Inside Diameter (mm)

| Rotor/Drum | Left | Right |
|------------|------|-------|
| Drum       |      |       |
| Drum       |      |       |
| Drum       |      |       |
| Drum       |      |       |

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

## Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Inspector: COX, JAMES EDWARD

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Aug-29 01:20 PM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations

## NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g., regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVP at the Commercial Vehicle Safety Enforcement.

CVSE0014

8/29/2025 1:20:57 PM MST