



Commercial Vehicle Inspection Report

Decal Number: PX12600
Decal Expiry Date: 2025-Dec-31
Inspection Number: 21176769

212-1

Inspection Result:
PASS

FACILITY:	EXCEL TRANSPORTATION INC. / P1009	INSP. TYPE:	Complete	INSP. START:	2024-Dec-12 03:24 PM PST
INSPECTOR:	VAN VLEET, CARSON / 300252	INSP. CLASS:	Class 2 - Heavy Vehicle with LGW 5501 kg or more	INSP. COMPLETE:	2024-Dec-12 05:00 PM PST
WORK ORDER #:		INSP. REASON:	Annual		
VEHICLE JUR:	British Columbia	REGI:	12825748	VIN:	3AKJGND17KDKL8351
PLATE #:	VP4420	UNIT/FLEET#:	16402	OWNER/LESSEE NAME:	Excel Transportation, Excel Transportation
LICENCED GVW(kg):	63500	BODY STYLE:	Truck Tractor	ADDRESS:	333 Ongman Road, 333 Ongman Road Prince George, British Columbia V2K 4K9, Canada
VEHICLE YEAR:	2019	ODOMETER:	689051 KM		
MAKE:	FREIGHTLIN	HUB ODOMETER:			
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:	Diesel		

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Repaired (same day)	Repair exhaust system leaks.
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Repaired (same day)	Repair RHS headlight.
Section 7 - Electrical System	Repaired (same day)	Repair electric horn.
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Repaired (same day)	Rebuild 5th wheel.
Section 11 - Other Vehicle Components	Not Applicable	

Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24L	Automatic	28.6	28.6	8			8	✓
2	Clamp	30L	Automatic	38.1	38.1	15	12	16	13	
3	Clamp	30L	Automatic	38.1	38.1	16	16	15	16	
Comment:				Comment:						

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	45	45	Lining (Shoe)	16	16	Drum		
2	60	60	Lining (Shoe)	13	13	Drum		
3	55	60	Lining (Shoe)	13	12	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Road Tester:

Inspector: VAN VLEET, CARSON Signature:

This Inspection Report was submitted to CVSE on 2024-Dec-12 05:20 PM PST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.