

## Commercial Vehicle COLUMBIA Inspection Report

Decal Number: Decal Expiry Date: Inspection Number: G.176402 2026-Jun-30 21379804

Inspection Result: PASS

821-

FACILITY:

GEAR-O-RAMA SUPPLY LTD. /

S11480

Kronlachner, Karl Joseph / 203489

INSP. TYPE: INSP. CLASS: Complete Class 3 - Trailer and Semi-Trailer INSP START INSP. COMPLETE: 2025-Jun-05 11:20 AM MST

INSPECTOR:

INSP. REASON: Annual

2025-Jun-05 12:11 PM MST

WORK ORDER #: VEHICLE JUR:

PLATE #:

R100016749 Alberta

REGI:

Passed

Passed Passed

Passed

Passed

Passed

Not Applicable

Not Applicable

UNIT/FLEET#:

PDT-01

OWNER/LESSEE NAME:

2DAHC6258JT019279

ECLIPSE E-LINE SERVICES INC. ECLIPSE E-LINE SERVICES INC

LICENCED GVW(kg): 0 VEHICLE YEAR:

2018

DOUBLE A

BODY STYLE: ODOMETER:

Trailer

ADDRESS:

VIN-

410-435 4 AVE SW

CALGARY, Alberta T2P3A8, Canada

MAKE: MODEL:

SHB758-40

BRAKE TYPE: FUEL TYPE:

HUB ODOMETER:

Not Applicable

Vehicle Identification (VIN)

Section 1 - Power Train Section 2 - Suspension Section 3 - Brake System Section 3A - Air Brakes Section 3H - Hydraulic Brakes Section 4 - Steering

Section 5 - Instruments and Auxiliary Equipment

Section 6 - Lamps

Repaired (same day)

REPAIRED LICENSE PLATE LIGHT, REPAIRED RIGHT SIDE CENTER SIGNAL/MARKER LIGHT

Section 7 - Electrical System

Passed Section 8 - Frame and Body Passed Section 9A - Tires Passed Section 9B - Wheels Passed Section 10 - Coupling Devices Passed Section 11 - Other Vehicle Components Passed

ir Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Iread Depth (mm)				
Axles	Туре	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	31.8	31.8	11	11	11	11	
2	Clamp	30	Automatic	31.8	31.8	11	11	11	11	
3	Clamp	30	Automatic	31.8	31.8	11	11	11	11	
Comment:						Comment:				

Air Brake Camshaf	t Rotation (deg	rees)	Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	20	20	Lining (Shoe)	21	21	Drum			
2	20	20	Lining (Shoe)	21	21	Drum			
3	20	20	Lining (Shoe)	21	21	Drum			
Comment:		1	Comment:			Comment: Air Brake Camsha Thickness or Drum Diameter		formed. Rotor	

Inspection Comments:

Has this Vehicle been road tested?

Kronlachner, Karl Joseph

Road Test Date Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Jun-05 02:19 PM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations, it is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any duestions about the collection of this information, you may contact the Sr. Manager, NSCVP at the Commercial Vehicle Safety Enforcement. CVSE0014

6/5/2025 2:19:44 PM MST