

035-1



Commercial Vehicle Inspection Report

Decal Number: GL32622
Decal Expiry Date: 2026-Jun-30
Inspection Number: 21588156

Inspection Result:

PASS

FACILITY: RATCHET CONTRACTING LTD / S16540
INSPECTOR: MILWARD, ADAM BRYCE / 112552
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual

INSP. START: 2025-Dec-01 11:52 AM PST
INSP. COMPLETE: 2025-Dec-01 12:52 PM PST

VEHICLE JUR: British Columbia
PLATE #: WR6915
LICENCED GVW(kg): 56000
VEHICLE YEAR: 2008
MAKE: KENWORTH
MODEL:

REGI: 00935606
UNIT/FLEET#:
BODY STYLE: Tank
ODOMETER: 674477 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 1NKDL40X58R934500
OWNER/LESSEE NAME: FORESTRY LTD, BOREAL WEST
ADDRESS: PO BOX 57
70 Mile House, British Columbia
V0K2K0, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Repaired (same day) REAR ENGINE MOUNTS
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) #2L SLACK ADJUSTER
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Repaired (same day) SWITCHES LOOSE IN DASH
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24L	Automatic	44	41	18			15	✓
2	Clamp	30	Automatic	55	51	15	15	17	17	
3	Clamp	30	Automatic	49	52	10	10	19	19	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	65	65
2	85	80
3	55	95

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	15	15
Lining (Shoe)	13	14
Lining (Shoe)	16	11

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Inspector: MILWARD, ADAM BRYCE

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Dec-01 01:52 PM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQV/P at the Commercial Vehicle Safety Enforcement

CVSE0014

12/1/2025 1:52:30 PM PST