



**BRITISH
COLUMBIA**

Commercial Vehicle Inspection Report

Decal Number: GK12894
Decal Expiry Date: 2026-Jul-31
Inspection Number: 21620436

Inspection Result:

PASS

FACILITY: ATS MECHANICAL INC. / S10460 INSP. TYPE: Complete INSP. START: 2026-Jan-06 07:40 AM PST
INSPECTOR: Nichols, Dean William / 200229 INSP. CLASS: Class 2 - Heavy Vehicle with LGVW INSP. COMPLETE: 2026-Jan-06 10:41 AM PST
WORK ORDER #: 5501 kg or more INSP. REASON: Semi-annual

VEHICLE JUR: British Columbia REG: 11579593 VIN: 1XPXD48X1GD333464
PLATE #: UNIT/FLEET: OWNER/LESSEE NAME: Agri-Trans Services Inc, Agri-Trans Services Inc
LICENCED GVW(kg): 63500 BODY STYLE: Truck Tractor ADDRESS: 2200 Kiron Ave
VEHICLE YEAR: 2016 ODOMETER: 827133 KM Armstrong, British Columbia
MAKE: PETERBILT HUB ODOMETER: V0E 1B0, Canada
MODEL: BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed with Caution	Engine oil leak near fuel pump, level 1 leak at time of inspection
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed with Caution	Steer tire at 4mm at time of inspection
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axes	Type	Size	Slack Adj.	Left	Right
1	Clamp	24L	Automatic	34	38
2	Clamp	30L	Automatic	34	40
3	Clamp	30L	Automatic	34	34

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
5			4	✓
8	8	10	10	
12	7	8	8	

Comment:

Air Brake Camshaft Rotation (degrees)

Axes	Left	Right
1	72	77
2	94	92
3	87	85

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	15	15
Lining (Shoe)	13	13
Lining (Shoe)	18	18

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Road Tester:

Inspector: Nichols, Dean William

Signature: _____

This Inspection Report was submitted to CVSE on 2026-Jan-06 10:41 AM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the St. Manager, NSQVSP at the Commercial Vehicle Safety Enforcement

CVSE014

1/6/2026 10:41:27 AM PST