



BRITISH
COLUMBIA

Commercial Vehicle
Inspection Report

Decal Number: GL11935
Decal Expiry Date: 2026-Jun-30
Inspection Number: 21591932

Inspection Result:
PASS

FACILITY: Walkers Repair Centre / S20307 INSP. TYPE: Complete INSP. START: 2025-Dec-01 06:00 PM MST
INSPECTOR: SCHAGER, ALBIN CARL / 106733 INSP. CLASS: Class 3 - Trailer and Semi-Trailer INSP. COMPLETE: 2025-Dec-04 06:00 AM MST
WORK ORDER #: INSP. REASON: Semi-annual

VEHICLE JUR: British Columbia REGI: 14449646 VIN: 2C92317E5J1086204
PLATE #: 70553K UNIT/FLEET #: OWNER/LESSEE NAME: Concrete LTD, KINETIC
LICENCED GVW(kg): 0 BODY STYLE: Dump Trailer ADDRESS: 4606 Columbia Lake Rd
VEHICLE YEAR: 2018 ODOMETER: Fairmont Hot Springs, British Columbia
MAKE: CANCADE HUB ODOMETER: V0B1L2, Canada
MODEL: PUP BRAKE TYPE: Air
FUEL TYPE:

| | |
|---|--|
| Vehicle Identification (VIN) | Passed |
| Section 1 - Power Train | Not Applicable |
| Section 2 - Suspension | Repaired (same day) Weld spring hanger |
| Section 3 - Brake System | Passed |
| Section 3A - Air Brakes | Passed |
| Section 3H - Hydraulic Brakes | Not Applicable |
| Section 4 - Steering | Not Applicable |
| Section 5 - Instruments and Auxiliary Equipment | Passed |
| Section 6 - Lamps | Passed |
| Section 7 - Electrical System | Passed |
| Section 8 - Frame and Body | Passed |
| Section 9A - Tires | Passed |
| Section 9B - Wheels | Passed |
| Section 10 - Coupling Devices | Passed |
| Section 11 - Other Vehicle Components | Passed |

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

| Axles | Type | Size | Slack Adj. | Tire Tread Depth (mm) | | | | | | | |
|-------|-------|------|------------|-----------------------|-------|---------|---------|---------|---------|----------|--|
| | | | | Left | Right | Outer L | Inner L | Inner R | Outer R | Steering | |
| 1 | Clamp | 30 | Automatic | 32 | 36 | 13 | 13 | 13 | 13 | 13 | |
| 2 | Clamp | 30 | Automatic | 32 | 33 | 10 | 10 | 10 | 10 | 10 | |
| 3 | Clamp | 30 | Automatic | 34 | 34 | 12 | 12 | 12 | 12 | 12 | |

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

| Axles | Left | Right | Brake Lining/Pad (mm) | | Rotor Thickness or Drum Inside Diameter (mm) | | | |
|-------|------|-------|-----------------------|---------------|--|-------|------------|------|
| | | | Lining/Pad | Lining/Pad | Left | Right | Rotor/Drum | Left |
| 1 | 50 | 50 | Lining (Shoe) | Lining (Shoe) | 17 | 17 | Drum | |
| 2 | 50 | 50 | Lining (Shoe) | Lining (Shoe) | 17 | 17 | Drum | |
| 3 | 60 | 60 | Lining (Shoe) | Lining (Shoe) | 15 | 15 | Drum | |

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: SCHAGER, ALBIN CARL

Road Test Date:
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Dec-04 07:01 AM MST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVP at the Commercial Vehicle Safety Enforcement

CVSE0014

12/4/2025 7:01:37 AM MST