



# Commercial Vehicle Inspection Report

Decal Number: GJ40425  
Decal Expiry Date: 2026-May-31  
Inspection Number: 21352793

Inspection Result:

**PASS**

FACILITY:	OCEAN TRAILER / S6173	INSP. TYPE:	Complete	INSP. START:	2025-May-15 11:00 AM PDT
INSPECTOR:	ILIC, ZORAN / 202362	INSP. CLASS:	Class 3 - Trailer and Semi-Trailer	INSP. COMPLETE:	2025-May-15 12:00 PM PDT
WORK ORDER #:	WO46232	INSP. REASON:	Annual		
VEHICLE JUR:	Alberta	REGI:		VIN:	1UYVS3531GG473722
PLATE #:	4YS477	UNIT/FLEET#:	66893	OWNER/LESSEE NAME:	C KEAY INVESTMENTS LTD, C KEAY INVESTMENTS LTD
LICENCED GVW(kg): 0		BODY STYLE:	Semi Trailer	ADDRESS:	234136 84 ST SE, 234136 84 ST SE ROCKY VIEW, Alberta T1X0K2, Canada
VEHICLE YEAR:	2016	ODOMETER:			
MAKE:	UTILITY	HUB ODOMETER:	198090 Miles		
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:	Not Applicable		

G17-2

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axes	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	32	32	6.4	7.9	7.1	7.1	
2	Clamp	30	Automatic	32	32	11.1	11.9	10.3	11.9	
3	Clamp	30	Automatic	32	34	7.1	7.9	6.4	5.6	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)				
Axes	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right		
1	30	30	Lining (Shoe)	21	21	Drum				
2	30	30	Lining (Shoe)	21	21	Drum				
3	30	75	Lining (Shoe)	21	14	Drum				

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

#### Inspection Comments:

Has this Vehicle been road tested? No

Inspector: ILIC, ZORAN

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-May-15 01:17 PM PDT  
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

5/15/2025 1:17:28 PM PDT