



# Commercial Vehicle Inspection Report

Decal Number: GK63159  
 Decal Expiry Date: 2026-Oct-31  
 Inspection Number: 21531220

A77-306  
 Inspection Result

**PASS**  
 TLF 3644

**FACILITY:** NOON DAY MOON / S10590 **INSP. TYPE:** Complete **INSP. START:** 2025-Oct-14 01:00 PM PDT  
**INSPECTOR:** Piper, David Donald JOHN / 101851 **INSP. CLASS:** Class 3 - Trailer and Semi-Trailer **INSP. COMPLETE:** 2025-Oct-14 02:30 PM PDT  
**WORK ORDER #:** 137809 **INSP. REASON:** Annual

**VEHICLE JUR:** British Columbia **REGI:** 13820163 **VIN:** 5JYFB4822JED06739  
**PLATE #:** 9V0V7Y **UNIT/FLEET#:** 3644 **OWNER/LESSEE NAME:** AMECO SERVICES INC, AMECO  
**LICENCED GVW(kg):** 0 **BODY STYLE:** Flat Deck Trailer **ADDRESS:** 101-6909 42 STREET, 101-6909 42 STREET  
**VEHICLE YEAR:** 2018 **ODOMETER:** LEDUC, Alberta  
**MAKE:** DORSEY **HUB ODOMETER:** T9E0W1, Canada  
**MODEL:** **BRAKE TYPE:** Air **FUEL TYPE:**

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Repaired (same day) FIX SOME LIGHTS
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

**Air Brake Chamber Type, Size and Push Rod Stroke (mm)**

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	32	33
2	Clamp	30	Automatic	33	33

Comment:

**Tire Tread Depth (mm)**

Outer L	Inner L	Inner R	Outer R	Steering
9	9	9	9	
14	13	13	14	

Comment:

**Air Brake Camshaft Rotation (degrees)**

Axles	Left	Right
1	25	15
2	20	20

Comment:

**Brake Lining/Pad (mm)**

Lining/Pad	Left	Right
Lining (Shoe)	19	19
Lining (Shoe)	20	20

Comment:

**Rotor Thickness or Drum Inside Diameter (mm)**

Rotor/Drum	Left	Right
Drum	0.00	0.00
Drum	0.00	0.00

Comment: NO DUST COVERS

**Inspection Comments:**

Has this Vehicle been road tested? No **Road Test Date:** **Road Tester:**  
**Inspector:** Piper, David Donald JOHN **Signature:**

This Inspection Report was submitted to CVSE on 2025-Oct-14 03:03 PM PDT  
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

**NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.**

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE014

10/14/2025 3:03:23 PM PDT

A77-