



# Commercial Vehicle Inspection Report

Decal Number: PY23361  
Decal Expiry Date: 2026-May-31  
Inspection Number: 21549601

CO2-2  
Inspection Result:  
**PASS**

**FACILITY:** NORTHERN B.C. TRUCKERS' / N5398  
**INSPECTOR:** CHRISTIANSON, LESLIE RYAN / 106407  
**WORK ORDER #:**

**INSP. TYPE:** Complete  
**INSP. CLASS:** Class 2 - Heavy Vehicle with LGVV 5501 kg or more  
**INSP. REASON:** Semi-annual

**INSP. START:** 2025-Nov-09 01:27 PM MST  
**INSP. COMPLETE:** 2025-Nov-09 02:53 PM MST

**VEHICLE JUR:** British Columbia  
**PLATE #:** WF3694  
**LICENCED GVW(kg):** 30000  
**VEHICLE YEAR:** 2000  
**MAKE:** INTERNATNA  
**MODEL:**

**REGI:** 11597378  
**UNIT/FLEET#:** 3060  
**BODY STYLE:** Giraffe Truck  
**ODOMETER:** 1 KM  
**HUB ODOMETER:**  
**BRAKE TYPE:** Air  
**FUEL TYPE:**

**VIN:** 1HTGLAHT9YH257734  
**OWNER/LESSEE NAME:** ARCTIC ARROW SERVICES LTD., N/A  
**ADDRESS:** 18509 96AVE  
Surrey, British Columbia  
V4N3P7, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) Lt r1 repair
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	20	Automatic	29	28	12			12	✓
2	Clamp	30	Automatic	33	36	20	19	19	20	
3	Clamp	30	Automatic	36	34	20	20	21	21	

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	47	40	Lining (Shoe)	18	19.5	Drum		
2	69	61	Lining (Shoe)	15	16	Drum		
3	62	57	Lining (Shoe)	16	16.5	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments: Km 125775  
Has this Vehicle been road tested? No  
Inspector: CHRISTIANSON, LESLIE RYAN  
Road Test Date:   
Road Tester:

This Inspection Report was submitted to CVSE on 2025-Nov-09 05:12 PM MST  
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.