

B05-6



Commercial Vehicle Inspection Report

Decal Number: **134845**
Decal Expiry Date: **2026-Aug-31**
Inspection Number: **21666688**

Inspection Result:
PASS

FACILITY: CHARLIES TRUCK REPAIR LTD / S2486
INSPECTOR: FELL, MARK DALE / 201512
WORK ORDER #:
INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual
INSP. START: 2026-Feb-17 08:00 AM MST
INSP. COMPLETE: 2026-Feb-17 10:00 AM MST

VEHICLE JUR: British Columbia
PLATE #: MS7380
PERMITTED GVW(kg): 26100
VEHICLE YEAR: 2019
MAKE: WESTERN ST
MODEL:
REGI: 12819552
UNIT/FLEET#: T235
BODY STYLE: Dump Truck
ODOMETER: 65982 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 5KKHALFG9KPKK1319
OWNER/LESSEE NAME: WHITE BEAR INDUSTRIES, LTD
ADDRESS: BOX 669 STN MAIN
Terrace, British Columbia
V8G4B8, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	30	30	18			15	✓
2	Clamp	30L	Automatic	30	30	21	20	20	20	
3	Clamp	30L	Automatic	30	30	8	9	12	10	

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	41	38	Lining (Shoe)	18	18	Drum		
2	51	48	Lining (Shoe)	16	16	Drum		
3	44	48	Lining (Shoe)	17	17	Drum		

Inspection Comments:
Has this Vehicle been road tested? **No**
Inspector: FELL, MARK DALE
Road Test Date:
Signature: 
Road Tester:

This Inspection Report was submitted to CVSE on 2026-Feb-17 02:27 PM MST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.