

D24-2



### Commercial Vehicle Inspection Report

Decal Number: GM76321  
 Decal Expiry Date: 2027-Feb-28  
 Inspection Number: 21876791

Inspection Result:  
**PASS**

FACILITY: K&A REPAIRS LTD / 519000  
 INSPECTOR: FATUM, KURTIS / 200655  
 WORK ORDER #:  
 INSP. TYPE: Complete  
 INSP. CLASS: Class 3 - Trailer and Semi-Trailer  
 INSP. REASON: Annual  
 INSP. START: 2025-Feb-25 01:00 PM PST  
 INSP. COMPLETE: 2025-Feb-25 02:00 PM PST

VEHICLE JUR: British Columbia  
 PLATE #: A1YBR2  
 LICENCED GVW(kg): 0  
 VEHICLE YEAR: 2005  
 MAKE: HEIL  
 MODEL:  
 REG#: 13988258  
 UNIT/FLEET#:   
 BODY STYLE: Tank Trailer  
 ODOMETER:  
 HUB ODOMETER:  
 BRAKE TYPE: Air  
 FUEL TYPE:  
 VIN: 5H1DL433305D105Z  
 OWNER/LESSEE NAME: CUNNINGHAM, SCOTT MICHAEL  
 ADDRESS: 4-2135 GUR#1 ST 5  
 Prince George, British Columbia  
 V2N2G2, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) REPLACED #1 AND #3 LH AND RH BRAKES AND DRUMS
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axes	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	33	32	10	9	11	10	
2	Clamp	30	Automatic	34	33	10	8	11	13	
3	Clamp	30	Automatic	32	34	12	12	11	10	

Comment: ADJUSTED ALL BRAKES TO PROPER SPEC.

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)			
Axes	Left	Right	Left	Right	Rotor/Drum	Left	Right	
1	20	20	Lining (Shoe)	22	Drum	420.00	420.00	
2	30	40	Lining (Shoe)	20	Drum	0.00	0.00	
3	20	20	Lining (Shoe)	22	Drum	420.00	420.00	

Comment: NEW BRAKES ON #1 AND #3 LH AND RH

Comment: NEW DRUMS ON #1 AND #3 LH AND RH; ONE OTHER DRUMS

Inspection Comments:  
 Has this Vehicle been road tested? No  
 Inspector: FATUM, KURTIS  
 Road Test Date:  
 Signature: Road Tester:

This Inspection Report was submitted in CUSE on 2025-Feb-25 02:45 AM PST  
 The Inspector's signature alone is verification that the vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION  
 The personal information collected on this form is collected under the authority of section 210 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purposes of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code Reg. regulating license, authorized inspectors, and designated inspection facilities. If you have any questions about the collection of this information, please contact the St. Manager, MCVPP at the Canadian Vehicle Safety Enforcement.  
 04570914  
 2006029-944-94-001 (01)