



Commercial Vehicle Inspection Report

R05-1

Decal Number: GM95685
 Decal Expiry Date: 2026-Oct-31
 Inspection Number: 21718439

Inspection Result:

PASS

2026-Apr-01 11:30 AM PDT
 2026-Apr-01 01:13 PM PDT

FACILITY: FOUNTAIN TIRE (QUESNEL) / S7175
 INSPECTOR: Johnson, James David / 110337
 WORK ORDER #:

INSP. TYPE: Complete
 INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
 INSP. REASON: Semi-annual

INSP. START:
 INSP. COMPLETE:

VEHICLE JUR: British Columbia
 PLATE #: RT3373
 LICENCED GVW(kg): 63500
 VEHICLE YEAR: 2005
 MAKE: KENWORTH
 MODEL:

REG#: 02934627
 UNIT/FLEET#: 116
 BODY STYLE: Truck Tractor
 ODOMETER: 139630 KM
 HUB ODOMETER:
 BRAKE TYPE: Air
 FUEL TYPE:

VIN: 1XXWD40X15R056162
 OWNER/LESSEE NAME: QUESNEL INDUSTRIAL TRANSPORT
 ADDRESS: 4252 COMEAU RD
 Quesnel, British Columbia
 V2J3W8 Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)				Steering		
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L		Inner R	Outer R
1	Clamp	24	Automatic	33	37	11.1			11.1	✓
2	Clamp	30	Automatic	37	35	11.1	11.9	6.7	12.7	
3	Clamp	30	Automatic	35	38	19.1	20.6	20.6	20.6	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)				Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right		Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	76	85		Lining (Shoe)	10.25	8.48	Drum		
2	75	65		Lining (Shoe)	13.03	14.01	Drum		
3	65	75		Lining (Shoe)	14.27	13.71	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed, Rotor Thickness or Drum Diameter not measured

Inspection Comments:

Has this Vehicle been road tested? No
 Inspector: Johnson, James David

Road Test Date:
 Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Apr-01 01:13 PM PDT
 The Inspector's signature above is certification that this vehicle has been inspected in accordance with the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 218 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing and issuing vehicle registrations and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating owners, authorized inspectors, and the general inspection facilities). If you have any questions about this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.