



Commercial Vehicle Inspection Report

Decal Number: GM89311
Decal Expiry Date: 2026-Sep-30
Inspection Number: 21685771

Inspection Result:
PASS

FACILITY: EDWARD BEETON REPAIR / S16910
INSPECTOR: BEETON, EDWARD / 112449
WORK ORDER #: 291710

INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual

INSP. START: 2026-Mar-05 07:00 AM PST
INSP. COMPLETE: 2026-Mar-05 10:00 AM PST

VEHICLE JUR: British Columbia
PLATE #: 1529KV
LICENCED GVW(kg): 63500
VEHICLE YEAR: 2008
MAKE: PETERBILT
MODEL:

REGI: 00809851
UNIT/FLEET#: 77
BODY STYLE: Tractor
ODOMETER: 957866 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 1XPWD49X78D753565
OWNER/LESSEE NAME: EASTEND, EASTEND HOLDINGS LTD
ADDRESS: 3751 OLD LAKELESE DR
Terrace, British Columbia
V8G5P4, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Repaired (same day) NEW CAB AIR BAGS
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Repaired (same day) NEW PS RESAVOR
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) MISC LIGHTS
Section 7 - Electrical System	Repaired (same day) NEW LOW AIR BUSSEER
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.
1	Clamp	24	Automatic
2	Clamp	30	Automatic
3	Clamp	30	Automatic

Comment:

Tire Tread Depth (mm)

Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
28	29	6			7	✓
31	32	12	10	11	10	
32	30	9	9	8	9	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	25	25
2	35	40
3	40	35

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	18	18
Lining (Shoe)	20	20
Lining (Shoe)	20	20

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured. REMOVED BACKING PLATES

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Road Tester:

Inspector: BEETON, EDWARD

Signature: _____

This Inspection Report was submitted to CVSE on 2026-Mar-05 10:03 AM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSED014
3/5/2026 10:03:51 AM PST