



Commercial Vehicle Inspection Report

Decal Number: GJ39511
Decal Expiry Date: 2026-Jul-31
Inspection Number: 21626236

Inspection Result:
PASS

W09-1

FACILITY: WESTECH DIESEL LTD / S13590 INSP. TYPE: Complete INSP. START: 2026-Jan-07 08:21 AM PST
 INSPECTOR: Albertson, Weston Maynard / 200060 INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more INSP. COMPLETE: 2026-Jan-11 12:21 PM PST
 WORK ORDER #: 39132 INSP. REASON: Semi-annual

VEHICLE JUR: British Columbia REGI: 03817742 VIN: 1FUJF6CK67DX37430
 PLATE #: PL8835 UNIT/FLEET#: OWNER/LESSEE NAME: Schultz, WES
 LICENCED GWV(kg): 63500 BODY STYLE: Truck Tractor ADDRESS: BOX 805, BOX 805
 VEHICLE YEAR: 2007 ODOMETER: 790975 KM Smithers, British Columbia
 MAKE: FREIGHTLIN HUB ODOMETER: V0J2N0, Canada
 MODEL: BRAKE TYPE: Air
 FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) REPLACED L3 AND R3 BRAKE POT
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Repaired (same day) REPLACED STEERING BOX SEAL AND POWERSTEERING LINE FROM PUMP TO RESEVOIR
Section 5 - Instruments and Auxiliary Equipment	Repaired (same day) REPLACED EXHAUST DRIVERSIDE YIPIE CLAMPAND P/S FLEX PIPE CLAMP REPLACED P/S UPPER AND LOWER CABMOUNTS
Section 6 - Lamps	Repaired (same day) REPLACED MULTIPLE CLEARANCE LIGHTS, REPAIRED MULTIPLE SECTIONS OF BAD WIRING FOR LIGHTS
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	26	25	11.5			10	✓
2	Clamp	30L	Automatic	33	33	17.5	16	16	14.5	
3	Clamp	30L	Automatic	37	37	19	18.5	19	19	

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	60	50	Lining (Shoe)	15.5	17	Drum		
2	60	70	Lining (Shoe)	14	15	Drum		
3	35	45	Lining (Shoe)	12	16	Drum		

Inspection Comments:
 Has this Vehicle been road tested? No Road Test Date:  Road Tester:
 Inspector: Albertson, Weston Maynard Signature: _____

This Inspection Report was submitted to CVSE on 2026-Jan-11 12:22 PMPST
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.