



Commercial Vehicle Inspection Report

Decal Number: GH81634
 Decal Expiry Date: 2027-Jan-31
 Inspection Number: 21639906

Inspection Result:
PASS

FACILITY: CULLEN WESTERN STAR TRUCKS LTD / S5079
 INSPECTOR: Berekoff, Donnie Lee / 112752
 WORK ORDER #: R401021332

INSP. TYPE: Complete
 INSP. CLASS: Class 3 - Trailer and Semi-Trailer
 INSP. REASON: Annual

INSP. START: 2026-Jan-23 10:34 AM PST
 INSP. COMPLETE: 2026-Jan-23 11:34 AM PST

520-11

VEHICLE JUR: Alberta
 PLATE #: 6NL5-6Z

REGI: 2A9JT4534YN125344
 UNIT/FLEET#: 18A
 OWNER/LESSEE NAME: SPRUCE HOLLOW HEAVY HAUL, SPRUCE HOLLOW HEAVY HAUL

LICENCED GVW(kg): 63500
 BODY STYLE: Other -< enter manual descriptor
 ADDRESS: PO BOX 28045 RPO MAHOGANY WAY
 Calgary, Alberta

VEHICLE YEAR: 2000
 MAKE: ASPEN
 MODEL: TRI JEEP

ODOMETER: T3M3C9, Canada
 HUB ODOMETER:
 BRAKE TYPE: Air
 FUEL TYPE: Not Applicable

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) Glad hand seals and small air tank replaced .
Section 3A - Air Brakes	Repaired (same day) Glad hand seals and small air tank replaced .
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Repaired (same day) #1 left outer . #1 right outer #2. #2 left inner . #2 right outer . replaced .
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	34	32	18	17	17	18	
2	Clamp	30	Automatic	33	34	16	18	16	18	
Comment:				Comment:						

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	40	40	Lining (Shoe)	21	21	Drum		
2	40	40	Lining (Shoe)	21	21	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:
 Has this Vehicle been road tested? No
 Inspector: Berekoff, Donnie Lee
 Road Test Date: _____
 Signature:  Road Tester: _____

This Inspection Report was submitted to CVSE on 2026-Jan-23 11:36 AM PST
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.
 The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSOVP at the Commercial Vehicle Safety Enforcement
 CVSE014
 1/23/2026 11:36:49 AM PST