

# Commercial Vehicle Inspection Report

Decal Number: GH81638  
 Decal Expiry Date: 2027-Jan-31  
 Inspection Number: 21641978

Inspection Result:  
**PASS**

FACILITY: CULLEN WESTERN STAR TRUCKS LTD / S5079  
 INSPECTOR: GREWAL, GURVINDER SINGH / 203307  
 WORK ORDER #:

INSP. TYPE: Complete  
 INSP. CLASS: Class 3 - Trailer and Semi-Trailer  
 INSP. REASON: Annual

INSP. START: 2026-Jan-23 07:30 AM PST  
 INSP. COMPLETE: 2026-Jan-26 09:00 AM PST

S20.33

VEHICLE JUR: Alberta  
 PLATE #: 6TF764  
 LICENCED GVW(kg): 0  
 VEHICLE YEAR: 2025  
 MAKE: FONTAINE  
 MODEL: MAGNITUDE

REGI: 36B  
 UNIT/FLEET#: 36B  
 BODY STYLE: Trailer  
 ODOMETER:  
 HUB ODOMETER:  
 BRAKE TYPE: Air  
 FUEL TYPE: Not Applicable

VIN: 13NE56309S35A4724  
 OWNER/LESSEE NAME: SPRUCE HALLOW, HEAVY HAUL  
 ADDRESS: PO BOX 28045 RPO MAHOGANY, PO BOX 28045 RPO MAHOGANY CALGARY, Alberta T3M3C9, Canada

Section	Result	Notes
Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Repaired (same day)	AXLE 2 RIGHT SIDE SHOCK SECURED
Section 3 - Brake System	Repaired (same day)	AXLE 1 LEFT SIDE AND AXLE 2 RIGHT SIDE SLACK ADJUSTERS REPLACED
Section 3A - Air Brakes	Repaired (same day)	AIR LEAK REPAIRED AXLE 1
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Not Applicable	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Repaired (same day)	FRONT RIGHT SIDE CORNER LIGHT REPLACED
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)					Steering
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R
1	Clamp	30	Automatic	38.1	38.1	12	12	13	13
2	Clamp	30	Automatic	41.3	38.1	11	9	8	8
3	Clamp	30	Automatic	41.3	41.3	15	16	14	16

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	71	68	Lining (Shoe)	16	16	Drum		
2	84	79	Lining (Shoe)	14	14	Drum		
3	88	83	Lining (Shoe)	14	14	Drum		

Inspection Comments:  
 Has this Vehicle been road tested? No  
 Inspector: GREWAL, GURVINDER SINGH  
 Road Test Date:  
 Signature: *Gurvinder Singh*  
 Road Tester:

This inspection report was submitted to CVSE on 2026-Jan-26 09:01 AM PST  
 The inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.