



# Commercial Vehicle Inspection Report

Decal Number: GH81631  
 Decal Expiry Date: 2027-Jan-31  
 Inspection Number: 21639179

Inspection Result:  
**PASS**

FACILITY: CULLEN WESTERN STAR TRUCKS LTD / S5079  
 INSPECTOR: SEROKA, NIKOLAI / 301041  
 WORK ORDER #: R401021321  
 INSP. TYPE: Complete  
 INSP. CLASS: Class 3 - Trailer and Semi-Trailer  
 INSP. REASON: Annual  
 INSP. START: 2026-Jan-21 10:17 PM PST  
 INSP. COMPLETE: 2026-Jan-22 03:41 PM PST

S20-34

VEHICLE JUR: Alberta  
 PLATE #: 6TF765  
 LICENCED GVW(kg): 0  
 VEHICLE YEAR: 2015  
 MAKE: FONTAINE  
 MODEL: 4 AXLE  
 REGI: 13NM0510XD3560394  
 UNIT/FLEET#: 36C  
 BODY STYLE: Trailer  
 ODOMETER:  
 HUB ODOMETER:  
 BRAKE TYPE: Air  
 FUEL TYPE: Not Applicable  
 VIN: 13NM0510XD3560394  
 OWNER/LESSEE NAME: LTD. SPRUCE HOLLOW HEAVY HULL  
 ADDRESS: PO BOX 28045 RPO MAHOGANY CALGARY, Alberta T3M3C9, Canada

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Repaired (same day)	REPLACE AIRBAGS
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Repaired (same day)	REPLACE S-CAM AND S-CAM BUSHING
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Repaired (same day)	REPAIR MARKER LAMP, REPAIR STROBE LIGHTS
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)					Tire Tread Depth (mm)					
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	44.5	44.5	14	14	14	14	
Comment:					Comment:					

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	55	55	Lining (Shoe)	16	16	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:  
 Has this Vehicle been road tested? No  
 Inspector: SEROKA, NIKOLAI  
 Road Test Date: \_\_\_\_\_  
 Signature:   
 Road Tester: \_\_\_\_\_

This Inspection Report was submitted to CVSE on: 2026-Jan-22 03:42 PM PST  
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

**NOTICE KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.**

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing the vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSE0014  
 1/22/2026 3:42:51 PM PST