



Commercial Vehicle Inspection Report

Decal Number: GH81628
 Decal Expiry Date: 2027-Jan-31
 Inspection Number: 21638208

Inspection Result:
PASS

FACILITY: CULLEN WESTERN STAR TRUCKS LTD / S5079
 INSPECTOR: LEBRUN, MATTHEW MERLE / 114863
 WORK ORDER #: 401021320

INSP. TYPE: Complete
 INSP. CLASS: Class 3 - Trailer and Semi-Trailer
 INSP. REASON: Annual

INSP. START: 2026-Jan-21 01:00 PM PST
 INSP. COMPLETE: 2026-Jan-22 08:09 AM PST

33B

VEHICLE JUR: Alberta
 PLATE #:
 LICENCED GVW(kg): 0
 VEHICLE YEAR: 2024
 MAKE: FONTANE
 MODEL: MAGNUDE

REGI:
 UNIT/FLEET#:
 BODY STYLE: Trailer
 ODOMETER:
 HUB ODOMETER:
 BRAKE TYPE: Air
 FUEL TYPE: Not Applicable

VIN: 67JE5330XR35A3497
 OWNER/LESSEE NAME: SPRUCE HOLLOW HEAVY HAUL LTD. .
 ADDRESS: PO BOX 28045 RPO MAHOGANY CALGARY, Alberta T3M 3C9, Canada

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Not Applicable	
Section 3A - Air Brakes	Repaired (same day)	REPAIR FOR #1 AND 2 AXLES NOT APPLYING BRAKES WHEN SUPPLY(EMERGENCY) AIR DISCONNECTED, TIGHTENED LOOSE ADJUSTER ANCHOR STUD #3 LH: SLACK
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Not Applicable	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Repaired (same day)	REPAIR FOR STROBE LIGHTS NOT WORKING
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30L	Automatic	38.1	34.8	11	10	10	11	
2	Clamp	30L	Automatic	38.1	38.1	10	10	9	9	
3	Clamp	30L	Automatic	38.1	38.1	10	10	10	10	

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	52	54	Lining (Shoe)	17	17	Drum		
2	82	65	Lining (Shoe)	13	14	Drum		
3	68	65	Lining (Shoe)	14	16	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:
 Has this Vehicle been road tested? No
 Road Test Date:
 Inspector: LEBRUN, MATTHEW MERLE
 Signature: 
 Road Tester:
 This Inspection Report was submitted to CVSE on 2026-Jan-22 08:10 AM PST
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for purposes, administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities), if you have any questions about the collection of this information, you may contact the Sr. Manager, T33CV, at the Commercial Vehicle Safety Enforcement

CVSE0014
 1/22/2026 @ 11:24 AM PST