

033-1



Commercial Vehicle Inspection Report

Decal Number: GK52778
Decal Expiry Date: 2026-May-31
Inspection Number: 21560990

Inspection Result:
PASS

FACILITY: RJAMES WESTERN STAR / S7341 **INSP. TYPE:** Complete **INSP. START:** 2025-Nov-05 10:00 AM PST
INSPECTOR: BURGGRAAF, BRANDON LEE / 300053 **INSP. CLASS:** Class 2 - Heavy Vehicle with LGVW 5501 kg or more **INSP. COMPLETE:** 2025-Nov-05 12:00 PM PST
WORK ORDER #: Kel017586 **INSP. REASON:** Semi-annual

VEHICLE JUR: British Columbia **REGI:** 13864518 **VIN:** 1HTXYAPT78J685233
PLATE #: RP7810 **UNIT/FLEET#:** 558 **OWNER/LESSEE NAME:** PITURA ENTERPRISES LTD, PITURA ENTERPRISES LTD
LICENCED GVW(kg): 50400 **BODY STYLE:** Dump Truck **ADDRESS:** 3139 APPALOOSA RD
VEHICLE YEAR: 2008 **ODOMETER:** 869602 KM Kelowna, British Columbia
MAKE: INTERNATNA **HUB ODOMETER:** V1V2G9, Canada
MODEL: **BRAKE TYPE:** Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Repaired (same day)	REAR DRIVE AXLE DIFF, INPUT U-JOINT HAS VERTICAL MOVEMENT
Section 2 - Suspension	Repaired (same day)	D/S STEER AXLE, LOWER SPRING PIN BUSHING SLID OUT FROM SPRING EYELET
Section 3 - Brake System	Repaired (same day)	FORWARD DRIVE AXLE, P/S, S-CAM TUBE SUPPORT BRACKET BROKEN.
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Repaired (same day)	D/S WINDSHIELD WIPER SPRAY NW
Section 6 - Lamps	Repaired (same day)	SUNVISER CLEARANCE LIGHT NW NO LICESNE PLATE LIGHT (MISSING)
Section 7 - Electrical System	Repaired (same day)	CABLE ENDS ON BATTERY TERMINALS LOOSE
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Repaired (same day)	LEVEL 3 OIL LEAK COMING FROM PTO

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	31	31	9			9	✓
2	Clamp	30	Automatic	44	50	6	5	4	5	
3	Clamp	30	Automatic	44	50	18	18	17	18	

Comment: _____

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	30	28	Lining (Shoe)	20	20	Drum		
2	43	55	Lining (Shoe)	20	18	Drum		
3	57	58	Lining (Shoe)	20	20	Drum		

Comment: _____

Inspection Comments:
 Has this Vehicle been road tested? No **Road Test Date:** _____ **Road Tester:** _____
Inspector: BURGGRAAF, BRANDON LEE **Signature:** _____

This Inspection Report was submitted to CVSE on 2025-Nov-07 02:45 PM PST
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION
 The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCV/P at the Commercial Vehicle Safety Enforcement
 CVSE0014
 11/7/2025 2:45:43 PM PST