



Commercial Vehicle Inspection Report

Decal Number: PA06106
Decal Expiry Date: 2027-Apr-30
Inspection Number: 21719409

023-H
Inspection Result:
PASS

FACILITY: NORTHERN B.C. TRUCKERS' / N5388
INSPECTOR: WASSENAAR, MICHAEL ANTHONY / 200357
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2026-Apr-01 11:45 AM MST
INSP. COMPLETE: 2026-Apr-01 12:15 PM MST

WORK ORDER #:

VEHICLE JUR: British Columbia
PLATE #: 55464K
LICENCED GVW(kg): 0
VEHICLE YEAR: 2024
MAKE: GERRY'S
MODEL:
REGI: 14289650
UNIT/FLEET#: S215
BODY STYLE: Lowbed Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2K9LB3564RL072001
OWNER/LESSEE NAME: ENVIORBORE DRILLING , LTD
ADDRESS: BOX 144
Fort St John, British Columbia
V1J 0K9, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Stack Adj.	Left	Right	Outer L	Innar L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	30	30	13	13	14	14	
2	Clamp	30	Automatic	30	30	13	13	13	13	
3	Clamp	30	Automatic	30	30	8	8	8	8	

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad		Left	Right	Rotor/Drum	Left	Right
1	0	0	Lining (Shoe)		16	16	Drum	420.00	420.00
2	0	0	Lining (Shoe)		16	15	Drum	420.00	420.00
3	0	0	Lining (Shoe)		16	16	Drum	420.00	420.00

Inspection Comments:
Has this Vehicle been road tested? No Road Test Date: _____ Road Tester: _____
Inspector: WASSENAAR, MICHAEL ANTHONY Signature:

This Inspection Report was submitted to CVSE on 2026-Apr-01 07:23 PM MST
The inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.