



Commercial Vehicle Inspection Report

Decal Number: PA06105
 Decal Expiry Date: 2026-Oct-31
 Inspection Number: 21719405

Inspection Result:
PASS

FACILITY: NORTHERN B.C. TRUCKERS' / N5398
INSPECTOR: WASSENAAR, MICHAEL ANTHONY / 200357
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVV 5501 kg or more
INSP. REASON: Semi-annual

INSP. START: 2026-Apr-01 11:00 AM MST
INSP. COMPLETE: 2026-Apr-01 11:45 AM MST

VEHICLE JUR: British Columbia
PLATE #: 70992P
LICENCED GVW(kg): 63500
VEHICLE YEAR: 2023
MAKE: KENWORTH
MODEL:

REGI: 14182165
UNIT/FLEET#: S107
BODY STYLE: Truck Tractor
ODOMETER: 153276 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 1XKZD40X7P956200
OWNER/LESSEE NAME: ENVIROBORE DRILLING, LTD
ADDRESS: BOX 144
 Fort St John, British Columbia
 V1J 0K9, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	28	28	15			15	✓
2	Clamp	30	Automatic	30	30	24	24	24	24	
3	Clamp	30	Automatic	30	30	24	24	24	24	

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	0	0	Lining (Shoe)	18	18	Drum	419.00	419.00
2	0	0	Lining (Shoe)	18	18	Drum	419.00	419.00
3	0	0	Lining (Shoe)	18	18	Drum	419.00	419.00

Inspection Comments:
 Has this Vehicle been road tested? No **Road Test Date:** _____ **Road Tester:** _____
Inspector: WASSENAAR, MICHAEL ANTHONY **Signature:** 

This Inspection Report was submitted to CVSE on 2026-Apr-01 07:17 PM MST
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.