



# Commercial Vehicle Inspection Report

Decal Number: GM02434  
 Decal Expiry Date: 2027-Mar-31  
 Inspection Number: 21688021

Inspection Result:

**PASS**

*H24-2*

FACILITY: INDUSTRIAL TRANSFORMERS / S7387  
 SECTOR: Murray, Austen Tate / 202879  
 WORK ORDER #:

INSP. TYPE: Complete  
 INSP. CLASS: Class 3 - Trailer and Semi-Trailer  
 INSP. REASON: Annual

INSP. START: 2026-Mar-06 11:45 AM PST  
 INSP. COMPLETE: 2026-Mar-06 12:45 PM PST

VEHICLE JUR: British Columbia  
 PLATE #: 97305K

REGI: 12486931  
 UNIT/FLEET#: 300

VIN: 2D9EC5535E1004020  
 OWNER/LESSEE NAME: TRUCKING, DEAD MAN'S ISLAND TRUCKING

LICENCED GVW(kg): 0  
 VEHICLE YEAR: 2014  
 MAKE: DELOUPE  
 MODEL: EC55

BODY STYLE: LOWBOY TRAILER  
 ODOMETER:  
 HUB ODOMETER:  
 BRAKE TYPE: Air  
 FUEL TYPE:

ADDRESS: PO BOX 1330, PO BOX 1330  
 Burns Lake, British Columbia  
 V0J1E0, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) NO LEFT SIGNAL
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	30	20	8	14	5	4	
2	Clamp	30	Automatic	40	32	14	12	16	14	
3	Clamp	30	Automatic	30	33	12	7	11	14	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	30	40	Lining (Shoe)	20	16	Drum		
2	30	30	Lining (Shoe)	19	19	Drum		
3	45	45	Lining (Shoe)	18	17	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

**Inspection Comments:**

Has this Vehicle been road tested? No  
 Inspector: Murray, Austen Tate  
 Road Test Date:  
 Signature: *[Signature]*  
 Road Tester:

This Inspection Report was submitted to CVSE on 2026-Mar-06 02:54 PMPST  
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

**KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.**

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement