

E96-1



Commercial Vehicle Inspection Report

Decal Number: GM76314
Decal Expiry Date: 2026-Aug-31
Inspection Number: 21666785

Inspection Result:
PASS

FACILITY: K&A REPAIRS LTD / S13960 INSP. TYPE: Complete INSP. START: 2026-Feb-17 02:00 PM PST
 INSPECTOR: FATUM, KURTIS / 200658 INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more INSP. COMPLETE: 2026-Feb-17 03:30 PM PST
 WORK ORDER #:

VEHICLE JUR: British Columbia REG#: 13363380 VIN: 1XPWD49X4AD113190
 PLATE #: SD2816 UNIT/FLEET#: 190 OWNER/LESSEE NAME: ZERO POINT CONTRACTING LTD., ZERO POINT CONTRACTING LTD.
 LICENCED GVW(kg): 47500 BODY STYLE: Truck Tractor ADDRESS: 1592 ABERDEEN RD
 VEHICLE YEAR: 2010 ODOMETER: 1274256 KM Prince George, British Columbia
 MAKE: PETERBILT HUB ODOMETER: V2K1G2, Canada
 MODEL: BRAKE TYPE: Air
 FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Repaired (same day) REPLACED ENGINE FAN
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) REPLACED #2 LH DUSTCOVER
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Repaired (same day) REPAIRED ABS
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axes	Type	Size	Stack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	28	28	20			16	✓
2	Clamp	30	Automatic	32	34	17	15	14	15	
3	Clamp	30	Automatic	33	33	14	15	11	12	

Comment: ADJUSTED ALL BRAKES TO PROPER SPEC Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axes	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	30	30	Lining (Shoe)	20	20	Drum		
2	30	50	Lining (Shoe)	22	17	Drum		
3	30	35	Lining (Shoe)	20	20	Drum		

Comment: Comment: Comment: Air Brake Camshaft Rotation performed, Rotor Thickness or Drum Diameter not measured

Inspection Comments:
 Has this Vehicle been road tested? No Road Test Date: 2/18/26 Road Tester:
 Inspector: FATUM, KURTIS Signature:

This Inspection Report was submitted to CVSE on 2026-Feb-18 02:07 PM PST
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION
 The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing the vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement
 CVSE0014
 2/18/2026 2:14:48 PM PST