



# Commercial Vehicle Inspection Report

Decal Number: GM76315  
Decal Expiry Date: 2027-Feb-28  
Inspection Number: 21668064

Inspection Result:  
**PASS**

FACILITY: K&A REPAIRS LTD / S13960  
INSPECTOR: FATUM, KURTIS / 200658  
WORK ORDER #:  
INSP. TYPE: Complete  
INSP. CLASS: Class 3 - Trailer and Semi-Trailer  
INSP. REASON: Annual  
INSP. START: 2026-Feb-18 08:00 AM PST  
INSP. COMPLETE: 2026-Feb-18 09:00 AM PST

VEHICLE JUR: British Columbia  
PLATE #: 11335K  
LICENCED GVW(kg): 0  
VEHICLE YEAR: 2014  
MAKE: EAGER BEAV  
MODEL: 2014  
REGI: 13365291  
UNIT/FLEET#: 290  
BODY STYLE: Lowbed Trailer  
ODOMETER:  
HUB ODOMETER:  
BRAKE TYPE: Air  
VIN: 112SD2510EL078720  
OWNER/LESSEE NAME: ZERO POINT CONTRACTING LTD., ZERO POINT CONTRACTING LTD.  
ADDRESS: 1592 ABERDEEN RD  
Prince George, British Columbia  
V2K1G2, Canada  
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Repaired (same day) REPAIRED AIR LEAK AT LEVELING VALVE
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) REPLACED #3 LH SPRING BRAKE AND #1 LH AND RH MAXI LINES
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	33	32	15	15	15	16	
2	Clamp	30	Automatic	34	32	17	16	15	16	
3	Clamp	30	Automatic	34	33	14	15	13	16	

Comment: ADJUSTED ALL BRAKES TO PROPER SPEC

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	30	40	Lining (Shoe)	20	19	Drum		
2	45	45	Lining (Shoe)	19	19	Drum		
3	35	45	Lining (Shoe)	20	19	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:  
Has this Vehicle been road tested? No  
Inspector: FATUM, KURTIS  
Road Test Date:   
Signature:   
Road Tester:

This Inspection Report was submitted to CVSE on 2026-Feb-18 02:32 PMPST  
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

**NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.**

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSOVP at the Commercial Vehicle Safety Enforcement

CVSE014  
2/18/2026 2:32:01 PMPST