



# Commercial Vehicle Inspection Report

Decal Number: GN14992  
 Decal Expiry Date: 2027-Apr-30  
 Inspection Number: 21749375

Inspection Result:  
**PASS**

FACILITY: K&A REPAIRS LTD / S13960 INSP. TYPE: Complete INSP. START: 2026-Apr-27 12:00 PM PDT  
 INSPECTOR: FATUM, KURTIS / 200658 INSP. CLASS: Class 3 - Trailer and Semi-Trailer INSP. COMPLETE: 2026-Apr-27 01:00 PM PDT  
 WORK ORDER #: INSP. REASON: Annual

VEHICLE JUR: Alberta REGI: VIN: 2M5131619S1035479  
 PLATE #: UNIT/FLEET#: OWNER/LESSEE NAME: ZERO POINT CONTRACTING LTD., ZERO POINT CONTRACTING LTD.  
 LICENCED GVW(kg): 14000 BODY STYLE: Flat-Deck Trailer ADDRESS: BOX 295  
 VEHICLE YEAR: 1995 ODOMETER: CAROLINE, Alberta  
 MAKE: MANAC HUB ODOMETER: TQM0M0, Canada  
 MODEL: DROP DECK BRAKE TYPE: Air  
 FUEL TYPE: Not Applicable

Vehicle Identification (VIN) Passed  
 Section 1 - Power Train Not Applicable  
 Section 2 - Suspension Passed  
 Section 3 - Brake System Passed  
 Section 3A - Air Brakes Repaired (same day) REPLACED #2 LH AND RH SPRING BRAKES  
 Section 3H - Hydraulic Brakes Not Applicable  
 Section 4 - Steering Not Applicable  
 Section 5 - Instruments and Auxiliary Equipment Passed  
 Section 6 - Lamps Repaired (same day) INSTALLED LICENSE PLATE LIGHT  
 Section 7 - Electrical System Passed  
 Section 8 - Frame and Body Passed  
 Section 9A - Tires Passed  
 Section 9B - Wheels Passed  
 Section 10 - Coupling Devices Passed  
 Section 11 - Other Vehicle Components Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	32	33	10	18	14	14	
2	Clamp	30	Automatic	34	32	13	13	13	13	
3	Clamp	30	Automatic	33	32	9	11	11	9	

Comment: ADJUSTED ALL BRAKES TO PROPER SPEC

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	65	45	Lining (Shoe)	16	19	Drum		
2	60	55	Lining (Shoe)	16	17	Drum		
3	50	45	Lining (Shoe)	17	19	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:  
 Has this Vehicle been road tested? No Road Test Date: 2/25/26 Road Tester:  
 Inspector: FATUM, KURTIS Signature:

This Inspection Report was submitted to CVSE on 2026-Apr-27 03:27 PM PDT  
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

**NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.**  
 The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing the vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSOVP at the Commercial Vehicle Safety Enforcement.  
 CVSE0014  
 4/27/2026 3:27:54 PM PDT