



# Commercial Vehicle Inspection Report

Decal Number: GL32066  
 Decal Expiry Date: 2026-Dec-31  
 Inspection Number: 21598698

Inspection Result:  
**PASS**

I 64.1

W041

**FACILITY:** P & R TRUCK CENTRE LTD. / S20272  
**INSPECTOR:** TAYLOR, RICHARD WILLIAM ROBERT / 107281  
**WORK ORDER #:** 4646

**INSP. TYPE:** Complete  
**INSP. CLASS:** Class 3 - Trailer and Semi-Trailer  
**INSP. REASON:** Annual

**INSP. START:** 2025-Dec-10 09:30 AM PST  
**INSP. COMPLETE:** 2025-Dec-10 11:00 AM PST

**VEHICLE JUR:** British Columbia  
**PLATE #:** A1D2R5  
**LICENCED GVW(kg):** 0  
**VEHICLE YEAR:** 1996  
**MAKE:** GERRYS  
**MODEL:**

**REGI:** 13372177  
**UNIT/FLEET#:**  
**BODY STYLE:** Flat Deck Trailer  
**ODOMETER:**  
**HUB ODOMETER:**  
**BRAKE TYPE:** Air  
**FUEL TYPE:**

**VIN:** 2A9PF4532TN125255  
**OWNER/LESSEE NAME:** RAMIDA ENTERPRISES, LTD  
**ADDRESS:** 7007 EAST SOOKE RD  
 Sooke, British Columbia  
 V9Z1A8, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) STROKE INDICATORS
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

### Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	38	38
2	Clamp	30	Automatic	38	38
3	Clamp	30	Automatic	38	38

### Tire Tread Depth (mm)

	Outer L	Inner L	Inner R	Outer R	Steering
1	8	10	16	11	
2	16	13	8	8	
3	10	10	11	10	

Comment:

Comment:

### Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	90	45
2	70	70
3	75	75

### Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	12	17
Lining (Shoe)	14	14
Lining (Shoe)	14	14

### Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

### Inspection Comments:

Has this Vehicle been road tested? No

Inspector: TAYLOR, RICHARD WILLIAM ROBERT

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Dec-10 11:51 AMPST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

### NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCV/P at the Commercial Vehicle Safety Enforcement

CVSE014

12/10/2025 11:51:51 AMPST