



BRITISH COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GH48927
Decal Expiry Date: 2026-Jun-30
Inspection Number: 21379747

Inspection Result: **PASS**

AD6-2

FACILITY: AMS TRUCK REPAIRS LTD. / S11890
 INSPECTOR: Spasiuk, Ryan / 301380
 WORK ORDER #: 1475

INSP. TYPE: Complete
 INSP. CLASS: Class 3 - Trailer and Semi-Trailer
 INSP. REASON: Annual

INSP. START: 2025-Jun-01 08:00 AM PDT
 INSP. COMPLETE: 2025-Jun-02 01:46 PM PDT

VEHICLE JUR: British Columbia
 PLATE #: 50291B
 LICENCED GVW(kg): 999999
 VEHICLE YEAR: 2007
 MAKE: DOEPKER
 MODEL:

REGI: 03621783
 UNIT/FLEET#: 672
 BODY STYLE: Flat Deck Trailer
 ODOMETER:
 HUB ODOMETER:
 BRAKE TYPE: Air
 FUEL TYPE:

VIN: 2DE-BFA2X71021371
 OWNER/LESSEE NAME: CANUSA TRANSPORTATION LTD, CANUSA
 ADDRESS: PO BOX 1080, Osoyoos, British Columbia, V0H1V0, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) Replaced multiple burnt out clearance lights.
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) Welded cracks on deck frame rails.
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Axles	Type	Size	Slack Adj.	Left	Right	Tire Tread Depth (mm)				Steering
1	Clamp	30	Automatic	35	32	Outer L	Inner L	Inner R	Outer R	
2	Clamp	30	Automatic	35	33	11.4	11.2	11.8	12	
Comment:				11.4 12.5 12.5 8.4						

Axles	Left	Right	Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)				
	80	45	Lining/Pad	Left	Right	Rotor/Drum		Left	Right
2	70	60	Lining (Shoe)	10	17	Drum			
			Lining (Shoe)	14	12	Drum			
Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.						

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: _____ Road Tester: _____

Inspector: Spasiuk, Ryan Signature: _____

This Inspection Report was submitted to CVSE on 2025-Jun-05 11:48 AM PDT
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.
 The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement
 CVSE0014
 6/5/2025 11:48:27 AM PDT

[Faint, illegible text on the left page, possibly bleed-through from the reverse side.]

[Faint, illegible text on the right page, possibly bleed-through from the reverse side.]