



# Commercial Vehicle Inspection Report

Decal Number: GN35422  
Decal Expiry Date: 2027-May-31  
Inspection Number: 21770628

Inspection Result:  
**PASS**

FACILITY: NOON DAY MOON / S10590      INSP. TYPE: Complete      INSP. START: 2026-May-13 07:00 AM PDT  
INSPECTOR: GAIR, SEAN MILLER / 301532      INSP. CLASS: Class 3 - Trailer and Semi-Trailer      INSP. COMPLETE: 2026-May-13 08:30 AM PDT  
WORK ORDER #: 138554      INSP. REASON: Annual

A77-130

VEHICLE JUR: Texas      REGI:      VIN: 13N248203J1525425  
PLATE #:      UNIT/FLEET#: TLD0716      OWNER/LESSEE NAME: AMERICAN EQUIPMENT COMPANY, AMECO  
LICENCED GVW(kg): 0      BODY STYLE: Flat-Deck Trailer      ADDRESS: 5200 GALVESTON RD, 5200 GALVESTON RD HOUSTON, Texas 77017, United States of America  
VEHICLE YEAR: 2018      ODOMETER:      HUB ODOMETER:      BRAKE TYPE: Air  
MAKE: FONTAINE      FUEL TYPE: Not Applicable  
MODEL: DECK

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxillary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

**Air Brake Chamber Type, Size and Push Rod Stroke (mm)**

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	32	32
2	Clamp	30	Automatic	31	32

Comment:

**Tire Tread Depth (mm)**

Outer L	Inner L	Inner R	Outer R	Steering
19	17	15	16	
17	15	14	15	

Comment:

**Air Brake Camshaft Rotation (degrees)**

Axles	Left	Right
1	35	45
2	40	40

Comment:

**Brake Lining/Pad (mm)**

Lining/Pad	Left	Right
Lining (Shoe)	17	17
Lining (Shoe)	16	16

Comment: NO DUST COVERS

**Rotor Thickness or Drum Inside Diameter (mm)**

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:  
Has this Vehicle been road tested? No      Road Test Date:      Road Tester:  
Inspector: GAIR, SEAN MILLER      Signature:

This Inspection Report was submitted to CVSE on 2026-May-13 09:58 AMPDT  
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.  
The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement  
CVSE014  
5/13/2026 9:59:04 AM PDT