

June R10-1



# Commercial Vehicle Inspection Report

Decal Number: PY23923  
Decal Expiry Date: 2026-Jul-31  
Inspection Number: 21621866

Inspection Result:  
**PASS**

FACILITY: NORTHERN B.C. TRUCKERS' / N5398  
INSPECTOR: PEREGOODOFF, DAVID JAMES / 112485  
INSP. TYPE: Complete  
INSP. CLASS: Class 3 - Trailer and Semi-Trailer  
INSP. REASON: Semi-annual  
INSP. START: 2026-Jan-07 11:15 AM MST  
INSP. COMPLETE: 2026-Jan-07 11:45 AM MST

**WORK ORDER #:**

VEHICLE JUR: British Columbia  
PLATE #: 94251K  
LICENCED GVW(kg): 999999  
VEHICLE YEAR: 2017  
MAKE: CROSSCOUNTRY  
MODEL:  
REGI: 12067625  
UNIT/FLEET#: 4496  
BODY STYLE: Dump Trailer  
ODOMETER:  
HUB ODOMETER:  
BRAKE TYPE: Air  
FUEL TYPE:  
VIN: 2C9SBS3WX9M183785  
OWNER/LESSEE NAME: ENERGETIC, SERVICES INC  
ADDRESS: 9315 ALASKA RD, 9315 ALASKA RD  
Fort St John, British Columbia  
V1J 1A3, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Repaired (same day) #2L OUTSIDE FLAT
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	40	37	9	9	18	19	
2	Clamp	30	Automatic	35	40	7	6	19	18	
3	Clamp	30	Automatic	37	42	12	13	13	13	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad		Left	Right	Rotor/Drum	Left	Right
1	65	60	Lining (Shoe)		16	17	Drum		
2	70	68	Lining (Shoe)		16	16	Drum		
3	79	48	Lining (Shoe)		14	18	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.			

Inspection Comments:  
Has this Vehicle been road tested? No  
Inspector: PEREGOODOFF, DAVID JAMES  
Road Test Date:                       
Signature: *David James*  
Road Tester:                     

This Inspection Report was submitted to CVSE on 2026-Jan-07 11:58 AM MST  
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.  
The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.  
CVSE0014  
17/2026 11:58:20 AM MST