



# Commercial Vehicle Inspection Report

Decal Number: **GM77470**  
 Decal Expiry Date: **2027-Mar-31**  
 Inspection Number: **21696084**

Inspection Result:  
**PASS**

FACILITY: FIRST TRUCK CENTRE INC. / S20092  
 INSPECTOR: MEIER, DILLON GORDON / 201220  
 WORK ORDER #: 14115  
 INSP. TYPE: Complete  
 INSP. CLASS: Class 3 - Trailer and Semi-Trailer  
 INSP. REASON: Annual  
 INSP. START: 2026-Mar-13 07:00 AM PDT  
 INSP. COMPLETE: 2026-Mar-13 08:30 AM PDT

VEHICLE JUR: British Columbia  
 PLATE #: 98728J  
 LICENCED GWV(kg): 999999  
 VEHICLE YEAR: 2012  
 MAKE: TRAILKING  
 MODEL:  
 REGI: 10503850  
 UNIT/FLEET#: **T66**  
 BODY STYLE: Flat Deck Trailer  
 ODOMETER:  
 HUB ODOMETER:  
 BRAKE TYPE: Air  
 FUEL TYPE:  
 VIN: 1TKC02834CM056956  
 OWNER/LESSEE NAME: LOAD'EM UP CONTRACTING LTD., LOAD'EM UP CONTRACTING LTD.  
 ADDRESS: 970 TERMINAL BLVD  
 Prince George, British Columbia  
 V2N 0H5, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	31.8	34.9	5.6	9.5	11.1	11.9	
2	Clamp	30	Automatic	34.9	34.9	12.7	11.1	11.9	10.3	
3	Clamp	30	Automatic	31.8	31.8	11.9	11.9	11.9	11.1	
Comment:				Comment:						

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Left	Right	Left	Right	Rotor/Drum	Left	Right
1	60	50	Lining (Shoe)	16	17		Drum		
2	65	65	Lining (Shoe)	16	16		Drum		
3	55	65	Lining (Shoe)	16	15		Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.			

Inspection Comments:  
 Has this Vehicle been road tested?  No  
 Inspector: MEIER, DILLON GORDON  
 Road Test Date: \_\_\_\_\_  
 Signature:   
 Road Tester: \_\_\_\_\_

This Inspection Report was submitted to CVSE on 2026-Mar-13 03:28 PM PDT  
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.