



Commercial Vehicle Inspection Report

Decal Number: PY25956
 Decal Expiry Date: 2026-Jul-31
 Inspection Number: 21621793

Inspection Result:
PASS

FACILITY: NORTHERN B.C. TRUCKERS' / N5398
INSPECTOR: CHRISTIANSON, LESLIE RYAN / 106407
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual

INSP. START: 2026-Jan-07 08:00 AM MST
INSP. COMPLETE: 2026-Jan-07 09:30 AM MST

VEHICLE JUR: British Columbia
PLATE #: PP2263
LICENCED GVW(kg): 63500
VEHICLE YEAR: 2012
MAKE: WESTERN ST
MODEL:

REGI: 10319239
UNIT/FLEET#: 20508
BODY STYLE: Truck Tractor
ODOMETER: 967608 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 5KJRALBG3CPBM3154
OWNER/LESSEE NAME: J Bueckert logging Ltd, .
ADDRESS: 11706 Maclean rd
 Fort St John, British Columbia
 V1j8b3, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Repaired (same day) Axle 4 pots
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Repaired (same day) Tie rod end r
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) Lights repaired 3x
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24L	Automatic	30	29	12			13	✓
2	Clamp	30L	Automatic	39	40	7	8	10	10	
3	Clamp	30L	Automatic	41	42	13	13	13	12	
4	Clamp	30L	Automatic	40	38	10	9	9	6	
Comment:						Comment:				

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.
 The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement
 CVSE0014
 1/7/2026 11:32:08 AM MST



Commercial Vehicle Inspection Report

Decal Number: PY25956
Decal Expiry Date: 2026-Jul-31
Inspection Number: 21621793

Inspection Result:
PASS

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	49	47	Lining (Shoe)	18.5	19	Drum		
2	94	90	Lining (Shoe)	11	12	Drum		
3	69	80	Lining (Shoe)	15	13	Drum		
4	72	69	Lining (Shoe)	14	15	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No Yes
 Road Test Date: _____ Road Tester: _____
 Inspector: CHRISTIANSON, LESLIE RYAN Signature: 

This Inspection Report was submitted to CVSE on 2026-Jan-07 11:32 AM MST
 The inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.