

D42-1



Commercial Vehicle Inspection Report

Decal Number: **GL64552**
Decal Expiry Date: **2027-Jun-30**
Inspection Number: **21800224**

Inspection Res
PAS

FACILITY: J.M. KEITH MECHANICAL / S4516 **INSP. TYPE:** Complete **INSP. START:** 2026-Jun-04 08:00 AM PDT
INSPECTOR: KEITH, JAMES MCKENZIE / 101992 **INSP. CLASS:** Class 2 - Heavy Vehicle with LGVW 5501 kg or more **INSP. COMPLETE:** 2026-Jun-04 10:30 AM PDT
WORK ORDER #: **INSP. REASON:** Annual

VEHICLE JUR: British Columbia **REGI:** 04538236 **VIN:** 1HTSDAANXVH488429
PLATE #: SA4349 **UNIT/FLEET#:** 009 **OWNER/LESSEE NAME:** Purmal Norman Troy, Troy Purmal
LICENCED GVW(kg): 14600 **BODY STYLE:** Tank **ADDRESS:** 12-3901 HWY 97 N
VEHICLE YEAR: 1997 **ODOMETER:** 57402 Miles **Quesnel, British Columbia**
MAKE: INTERNATNA **HUB ODOMETER:** V2J6W6, Canada
MODEL: **BRAKE TYPE:** Air **FUEL TYPE:**

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed with Caution Engine oil pan gasket leaking. Transmission pan gasket leaking.
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) Daytime running lights not working; module replaced for daytime running lights.
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	31	32	16			15	✓
2	Clamp	30	Automatic	30	29	15	17	20	20	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	45	45	Lining (Shoe)	20	20	Drum			
2	45	40	Lining (Shoe)	20	20	Drum			
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.			

Inspection Comments:
Has this Vehicle been road tested? No **Road Test Date:** James Keith **Road Tester:**
Inspector: KEITH, JAMES MCKENZIE **Signature:**

This Inspection Report was submitted to CVSE on 2026-Jun-04 12:01 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.