

243-1



# Commercial Vehicle Inspection Report

Decal Number: GM44333  
Decal Expiry Date: 2026-Aug-31  
Inspection Number: 21674834

Inspection Result:  
**PASS**

FACILITY: R.JAMES MANAGEMENT / S7339 INSP. TYPE: Complete  
INSPECTOR: SKILLEN, COLIN DAVID / 202081 INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more  
WORK ORDER #: RA101000480 INSP. REASON: Semi-annual  
INSP. START: 2026-Feb-24 04:11 PM PST  
INSP. COMPLETE: 2026-Feb-24 06:11 PM PST

VEHICLE JUR: British Columbia REGI: 10302870 VIN: 1FUJGNDR1COBJ5110  
PLATE #: WY3717 UNIT/FLEET#: OWNER/LESSEE NAME: CROMBIE TRANSPORT LTD,  
LICENCED GWW(kg): 63500 BODY STYLE: Logging Truck ADDRESS: 10 DAVOREN RD  
VEHICLE YEAR: 2012 ODOMETER: 808468 KM Clearwater, British Columbia  
MAKE: FREIGHTLIN HUB ODOMETER: v0e 1n2, Canada  
MODEL: BRAKE TYPE: Air  
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

### Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24	Automatic	38	37
2	Clamp	30L	Automatic	39	37
3	Clamp	30L	Automatic	40	37

Comment:

### Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
15			16	✓
12	12	11	12	
10	13	12	10	

Comment:

### Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	75	50
2	50	90
3	28	63

Comment:

### Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	11	15
Lining (Shoe)	15	10
Lining (Shoe)	18	16

Comment:

### Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

### Inspection Comments:

Has this Vehicle been road tested? No

Inspector: SKILLEN, COLIN DAVID

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Feb-24 06:13 PM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

### NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCV/P at the Commercial Vehicle Safety Enforcement

CVSE0014

2/24/2026 6:13:09 PM PST