


225-1



Commercial Vehicle Inspection Report

Decal Number: GMD1943
Decal Expiry Date: 2020-Aug-31
Inspection Number: 21689918

Inspection Result:

408 PASS

2020-Feb-10 04:15 AM PST
2020-Feb-10 06:00 AM PST

FACILITY: FOUNTAIN TIRE (QUESNEL) /
S7175
INSPECTOR: Johnson, James David / 110337
WORK ORDER #:

INSR. TYPE: Complete
INSR. CLASS: Class 2 - Heavy Vehicle with LGVW
INSR. REASON: Semi-annual
INSR. START: 2020-Feb-10 04:15 AM PST
INSR. COMPLETE: 2020-Feb-10 06:00 AM PST

VEHICLE JUR: British Columbia
PLATE #: XB1144
LICENCED GVW(kg): 43110
VEHICLE YEAR: 1989
MAKE: KENWORTH
MODEL:

REGI: 06214310
UNIT/FLEET#: H-08
BODY STYLE: Dump Truck
ODOMETER: 872875 KM
MUR ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2NKWL8DX8KM922234
OWNER/LESSEE NAME: PRESNO CONSTRUCTION, LTD.
ADDRESS: 1139 CARSON PIT RD
Oquesnel, British Columbia
V2J7H2, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Stroke Adj.	Left	Right	Tire Tread Depth (mm)	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Manual	34	33	13.5	13.5	16.3	16.7	16.7	✓
2	Clamp	30	Automatic	35	36	15.9	15.9	16.3	16.7	16.7	
3	Clamp	30	Automatic	34	33	15.1	15.1	15.1	15.1	9.5	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	45	35
2	65	70
3	65	60

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	18.22	18.8
Lining (Shoe)	14.31	14.1
Lining (Shoe)	14.21	18.11

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Inspector: Johnson, James David

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2020-Feb-10 06:15 AM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 21 of the Motor Vehicle Act Regulations. It is provided for the purpose of vehicle safety and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. requesting camera, authorized inspectors, and designated inspection facilities). If you have any questions about this collection of information, you may contact the British Columbia Motor Vehicle Safety Enforcement (MVE) at 1-800-663-3800.

CVSE014

21022020 06:15 AM PST