



Commercial Vehicle Inspection Report

Decal Number: GN82775
Decal Expiry Date: 2026-Dec-31
Inspection Number: 21822476

Inspection Result:
PASS

T29-1

FACILITY:	BABINE TRUCK & EQUIPMENT LTD. / S20190	INSP. TYPE:	Complete	INSP. START:	2026-Jun-22 08:00 AM PDT
INSPECTOR:	OOSTERHOFF, CLARENCE PETER / 102114	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2026-Jun-23 01:34 PM PDT
WORK ORDER #:	58394	INSP. REASON:	Semi-annual		

VEHICLE JUR:	British Columbia	REGI:	12405521	VIN:	1NKZX4EX2JJ991356
PLATE #:	XW7427	UNIT/FLEET#:	V26	OWNER/LESSEE NAME:	FINLOC 2000 INC. (LSR), WEST HORIZON CONTRACTING (LSE)
LICENCED GVW(kg):	63500	BODY STYLE:	Dump Truck	ADDRESS:	PO BOX 3430
VEHICLE YEAR:	2018	ODOMETER:	565155 KM		Smithers, British Columbia
MAKE:	KENWORTH	HUB ODOMETER:			V0J2N0, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)					Steering
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R		
1	Clamp	24L	Automatic	25.4	25.4	9			11	✓	
2	Clamp	30L	Automatic	28.6	28.6	9	7	8	10		
3	Clamp	30L	Automatic	28.6	28.6	16	16	12	14		
4	Clamp	30L	Automatic	38.1	38.1	18	16	21	20		
Comment:						Comment:					

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

6/23/2026 1:38:15 PM PDT



Commercial Vehicle Inspection Report

Decal Number: GN82775
Decal Expiry Date: 2026-Dec-31
Inspection Number: 21822476

Inspection Result:
PASS

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	95	85	Lining (Shoe)	10	14	Drum		
2	20	25	Lining (Shoe)	20	20	Drum		
3	25	35	Lining (Shoe)	19	18	Drum		
4	75	60	Lining (Shoe)	14	15	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date:  Road Tester:
Inspector: OOSTERHOFF, CLARENCE PETER Signature:

This Inspection Report was submitted to CVSE on 2026-Jun-23 01:38 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVP of the Commercial Vehicle Safety Enforcement.

CVSE014

6/23/2026 1:38:15 PM PDT