



Commercial Vehicle Inspection Report

T17

Decal Number: GM11111
Decal Expiry Date: 2026-Oct-31
Inspection Number: 21729878

T29-2
Inspection Result:
PASS

FACILITY: INLAND TRUCK & EQUIPMENT LTD. / S20294
INSPECTOR: Roersma, Michael Curtis / 203575
WORK ORDER #: 94
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Semi-annual
INSP. START: 2026-Apr-10 04:00 PM PDT
INSP. COMPLETE: 2026-Apr-10 06:00 PM PDT

VEHICLE JUR: British Columbia
PLATE #: 37696K
REGI: 04429701
UNIT/FLEET#:
VIN: 2N9EDB3E69L055541
OWNER/LESSEE NAME: SUMMIT PACIFIC RENTALS LTD. (LSR), WEST HORIZON CONTRACTING IN (LSE)
PERMITTED GVW(kg): 999999
VEHICLE YEAR: 2009
MAKE: NAHANNI
MODEL:
BODY STYLE: Dump Trailer
ADDRESS: PO BOX 3430, 2943 HWY 16 Smithers, British Columbia V0J 2N0, Canada
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Repaired (same day) REPLACED SPRING SLIPPER BOLTS ON LS
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	35	35
2	Clamp	30	Automatic	40	36
3	Clamp	30	Automatic	38	36

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
8	8	12	12	
7	12	12	12	
12	12	12	12	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	35	35
2	65	40
3	50	35

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	18	16
Lining (Shoe)	14	18
Lining (Shoe)	16	18

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Inspector: Roersma, Michael Curtis

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Apr-11 08:00 AM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

4/11/2026 8:00:14 AM PDT