

BRITISH
COLUMBIA**Commercial Vehicle
Inspection Report**Decal Number: GM72748
Decal Expiry Date: 2027-Apr-30
Inspection Number: 21750324

Inspection Result:

PASS

FACILITY:	BABINE TRUCK & EQUIPMENT LTD. / S20190	INSP. TYPE:	Complete	INSP. START:	2026-Apr-28 09:05 AM PDT
INSPECTOR:	Wierenga, Edward John / 110282	INSP. CLASS:	Class 3 - Trailer and Semi-Trailer	INSP. COMPLETE:	2026-Apr-28 10:40 AM PDT
WORK ORDER #:	58046	INSP. REASON:	Annual		
VEHICLE JUR:	British Columbia	REGI:	12230833	VIN:	2B925TT30H1001089
PLATE #:	89815J	UNIT/FLEET#:	T10	OWNER/LESSEE NAME:	WEST HORIZON CONTRACTING INC. WEST HORIZON CONTRACTING INC
LICENCED GVW(kg):	0	BODY STYLE:	Flat Deck Trailer	ADDRESS:	BOX 3430 SMITHERS BC Smithers, British Columbia V0J2N0, Canada
VEHICLE YEAR:	2018	ODOMETER:			
MAKE:	BWS/EZ-2-L	HUB ODOMETER:			
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	34.9	38.1
2	Clamp	30	Automatic	31.8	31.8
3	Clamp	30	Automatic	28.6	31.8

Comment:

Tire Tread Depth (mm)

	Outer L	Inner L	Inner R	Outer R	Steering
	6.4	6.4	5.6	7.1	
	11.9	9.5	7.9	8.7	
	11.9	11.9	9.5	11.9	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	50	57
2	33	46
3	64	49

Comment:

Brake Lining/Pad (mm)

	Lining/Pad	Left	Right
	Lining (Shoe)	18	17.5
	Lining (Shoe)	18.5	18
	Lining (Shoe)	17	18

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

	Rotor/Drum	Left	Right
	Drum		
	Drum		
	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Inspector: Wierenga, Edward John

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Apr-28 10:43 AM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVP at the Commercial Vehicle Safety Enforcement

CVSE014

4/28/2026 10:43:33 AM PDT