

BRITISH
COLUMBIACommercial Vehicle
Inspection ReportDecal Number: GL69230
Decal Expiry Date: 2026-Sep-30
Inspection Number: 21697844

Inspection Result:

PASS

FACILITY: BILL'S HEAVY DUTY / S0243 INSP. TYPE: Complete INSP. START: 2026-Mar-09 10:00 AM PDT
 INSPECTOR: BUCHAN, EDWARD DAVID / 114449 INSP. CLASS: Class 2 - Heavy Vehicle with LGVW INSP. COMPLETE: 2026-Mar-16 12:52 PM PDT
 WORK ORDER #: RB23195 INSP. REASON: Semi-annual

VEHICLE JUR: British Columbia REGI: 12945421 VIN: 1HTWNAZT1BJ35198
 PLATE #: VT4376 UNIT/FLEET#: 422 OWNER/LESSEE NAME: KAYS ROAD CONTRACTING LTD.,
 LICENCED GVW(kg): 26000 BODY STYLE: Tank ADDRESS: 3521 YMIR ROAD
 VEHICLE YEAR: 2011 ODOMETER: 189451 KM Nelson, British Columbia
 MAKE: INTERNATNA HUB ODOMETER: VIL 6Z4, Canada
 MODEL: BRAKE TYPE: Air
 FUEL TYPE:

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Repaired (same day)	REPLACE LEAKING 1R SERVICE LINE
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Repaired (same day)	REPLACE LEAKING STEERING BOX
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Not Applicable	
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axes	Type	Size	Slack Adj.	Left	Right	Tire Tread Depth (mm)				Steering
						Outer L	Inner L	Inner R	Outer R	
1	Clamp	24L	Automatic	40	40	11			14	✓
2	Clamp	30L	Automatic	35	37	11	11	12	12	
3	Clamp	30L	Automatic	36	42	15	15	12	14	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axes	Left	Right	Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)			
			Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	25	25	Lining (Shoe)	19	19	Drum		
2	60	70	Lining (Shoe)	14	13	Drum		
3	70	80	Lining (Shoe)	13	12	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
 Inspector: BUCHAN, EDWARD DAVID

Road Test Date:

Signature: *Ed David*

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Mar-16 12:54 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement

CVSE/014

3/16/2026 12:54:36 PM PDT