



Commercial Vehicle Inspection Report

Decal Number: GM22920
Decal Expiry Date: 2027-Jan-31
Inspection Number: 21622921

Inspection Result:
PASS

FACILITY:	BOB LAWRENCE TRUCK & EQUIPMENT / S6131	INSP. TYPE:	Complete	INSP. START:	2026-Jan-07 02:49 PM PST
INSPECTOR:	Badgley, James Scott / 108870	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2026-Jan-08 07:52 AM PST
WORK ORDER #:	35895	INSP. REASON:	Annual		
VEHICLE JUR:	British Columbia	REGI:	02448039	VIN:	1HTMKAAN95H119124
PLATE #:	DR1557	UNIT/FLEET#:		OWNER/LESSEE NAME:	FREDEX CONSTRUCTION, INC.
LICENCED GVW(kg):	25000	BODY STYLE:	Dump Truck	ADDRESS:	1-140 ADAMS ROAD
VEHICLE YEAR:	2005	ODOMETER:	455091 KM		Kelowna, British Columbia
MAKE:	INTERNATNA	HUB ODOMETER:			V1X7R2, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) BOX UP LIGHT NOT WORKING
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Tire Tread Depth (mm)				Steering
						Outer L	Inner L	Inner R	Outer R	
1	Clamp	20L	Automatic	32	32	11			10	✓
2	Clamp	30L	Automatic	32	32	7	5	4	5	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	58	62
2	65	68

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	16	16
Lining (Shoe)	16	15

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum	15.07	15.07
Drum	16.57	16.57

Comment:

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Jan-08 08:52 AMPST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement.

CVSE014

1/8/2026 8:52:49 AMPST