

BRITISH
COLUMBIACommercial Vehicle
Inspection Report
 Decal Number: GM07839
 Decal Expiry Date: 2026-Dec-31
 Inspection Number: 21591860

Inspection Result:

PASS

FACILITY:	A & R MOBILE TRUCK REPAIR LTD / S12450	INSP. TYPE:	Complete	INSP. START:	2025-Dec-02 07:30 PM PST
INSPECTOR:	Nelson, Jerry John / 201387	INSP. CLASS:	Class 3 - Trailer and Semi-Trailer	INSP. COMPLETE:	2025-Dec-02 08:30 PM PST
WORK ORDER #:		INSP. REASON:	Annual		

VEHICLE JUR:	Alberta	REGI:		VIN:	1U1VS2537FG184806
PLATE #:		UNIT/FLEET#:	53H27	OWNER/LESSEE NAME:	OVERLAND WEST FREIGHT LINES LTD.,
LICENCED GVW(kg):	46500	BODY STYLE:	Van	ADDRESS:	25535 111 AVE. Acheson, Alberta T7X 6C8, Canada
VEHICLE YEAR:	2015	ODOMETER:			
MAKE:	VEITTY	PUB ODOMETER:			
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:	Not Applicable		

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Repaired (same day)	REPLACE #1 AXLE RT BRAKE CHAMBER AND BOTH #2 BRAKE CHAMBERS, SECURE AIR LINES
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Not Applicable	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Repaired (same day)	REPAIR TAIL LIGHTS
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Stack Adj.	Left	Right	Tire Tread Depth (mm)				Steering
						Outer L	Inner L	Inner R	Outer R	
1	Clamp	30	Automatic	34	34	7	7	7	8	
2	Clamp	30	Automatic	34	34	8	8	8	8	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	55	55
2	50	50

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	17	17
Lining (Shoe)	18	18

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Dec-03 07:15 PM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSGVIP at the Commercial Vehicle Safety Enforcement.

CVSE014

12/3/2025 7:15:10 PM PST

