



Commercial Vehicle Inspection Report

Decal Number: GN75519
Decal Expiry Date: 2027-Jun-30
Inspection Number: 21797924

Inspection Result:
PASS

FACILITY: TWISTED METAL MECHANICS LTD. / S20269
INSPECTOR: BOLIVAR, MICHAEL BRANDON / 202902
WORK ORDER #: 325

INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual

INSP. START: 2026-Jun-03 04:00 AM MST
INSP. COMPLETE: 2026-Jun-03 05:00 AM MST

VEHICLE JUR: Alberta
PLATE #:
LICENCED GVW(kg): 99999
VEHICLE YEAR: 2019
MAKE: DELOUPE
MODEL: EN12

REGI:
UNIT/FLEET#: 4B-3
BODY STYLE: Semi Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE: Not Applicable

VIN: 2D9EN1215K1004049
OWNER/LESSEE NAME: AMA RENTALS, AMA
ADDRESS: 101-57 721071 RNG RD 53
GRAND PRAIRE, Alberta
T8X0N4, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	37	39	12	11	12	12	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	48	52	Lining (Shoe)	14	14	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:
Has this Vehicle been road tested? No
Inspector: BOLIVAR, MICHAEL BRANDON
Road Test Date:
Signature: *M. Bolivar*
Road Tester:

This Inspection Report was submitted to CVSE on 2026-Jun-03 07:54 AM MST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE0014

6/3/2026 7:54:49 AM MST

