



Commercial Vehicle Inspection Report

Decal Number: GP56228
Decal Expiry Date: 2027-Feb-28
Inspection Number: 21893516

Inspection Result:
PASS

FACILITY: Walkers Repair Centre / S20307 INSP. TYPE: Complete INSP. START: 2026-Aug-19 03:15 PM MDT
INSPECTOR: SCHAGER, ALBIN CARL / 106733 INSP. CLASS: Class 2 - Heavy Vehicle with LGVW INSP. COMPLETE: 2026-Aug-24 12:15 PM MDT
WORK ORDER #: INSP. REASON: Semi-annual

VEHICLE JUR: British Columbia REGI: 14367685 VIN: 1XK1D40X7RJ974888
PLATE #: 88165P UNIT/FLEET#: 246 OWNER/LESSEE NAME: Contracting LTD, CS McLean
LICENCED GVW(kg): 63500 BODY STYLE: Truck Tractor ADDRESS: PO Box 176, 4819 Crescentwood DR
VEHICLE YEAR: 2024 ODOMETER: 396617 KM Edgewater, British Columbia
MAKE: KENWORTH HUB ODOMETER: V0A1E0, Canada
MODEL: BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Repaired (same day) New left front wheel seal
Section 2 - Suspension	Repaired (same day) New bushings #2, #3 rear axel
Section 3 - Brake System	Repaired (same day) 2 new pots #2 axel #3 left
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Repaired (same day) New drag link
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24	Automatic	32	33
2	Clamp	30L	Automatic	36	35
3	Clamp	30L	Manual	35	37

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
15			15	✓
8	10	8	8	
10	10	8	8	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	40	40
2	40	40
3	40	40

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	19	19
Lining (Shoe)	19	19
Lining (Shoe)	19	19

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Road Tester:
Inspector: SCHAGER, ALBIN CARL Signature:

This Inspection Report was submitted to CVSE on 2026-Aug-24 02:16 PM MDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE0014

8/24/2026 2:16:54 PM MDT