



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: PA09583
Decal Expiry Date: 2026-Oct-31
Inspection Number: 21740928

B16-1
Inspection Result:
PASS

FACILITY:	NORTHERN B.C. TRUCKERS' / N5398	INSP. TYPE:	Complete	INSP. START:	2026-Apr-21 08:30 AM MST
INSPECTOR:	SCHROEDER, COLIN LESLIE / 109354	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2026-Apr-21 09:30 AM MST
WORK ORDER #:		INSP. REASON:	Semi-annual		

VEHICLE JUR:	British Columbia	REGI:	10921307	VIN:	1NKDX4TX6ER867226
PLATE #:	HX2165	UNIT/FLEET#:	SH127	OWNER/LESSEE NAME:	SCOTT HYDRO-VAC, LTD
LICENCED GVW(kg):	36810	BODY STYLE:	Tank	ADDRESS:	PO BOX 341 RPO DOWNTOWN
VEHICLE YEAR:	2014	ODOMETER:	307864 KM		Fort St John, British Columbia
MAKE:	KENWORTH	HUB ODOMETER:			V1J6W7, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Not Applicable
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24	Automatic	30	29
2	Clamp	30	Automatic	35	34
3	Clamp	30	Automatic	36	35
4	Clamp	30	Automatic	36	37

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
21			21	✓
23	23	23	23	
14	14	14	14	
17	17	17	17	

Comment:

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 218 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement.

CVSB014

4/21/2026 1:22:34 PM MST

Commercial Vehicle Inspection Report

Decal Number: PA09583
Decal Expiry Date: 2026-Oct-31
Inspection Number: 21740928

Inspection Result:
PASS

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	48	49	Lining (Shoe)	17	17	Drum		
2	60	62	Lining (Shoe)	16	16	Drum		
3	64	66	Lining (Shoe)	15	15	Drum		
4	63	62	Lining (Shoe)	16	16	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments: SYSTEM DOWN

Has this Vehicle been road tested? No Road Test Date:  Road Tester:
Inspector: SCHROEDER, COLIN LESLIE Signature:

This Inspection Report was submitted to CVSE on 2026-Apr-21 01:22 PM MST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSED014

4/21/2026 1:22:34 PM MST