



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GN43525
Decal Expiry Date: 2026-Dec-31
Inspection Number: 21799908

Inspection Result:

PASS

FACILITY: VAN DEURSEN DIESEL LTD. / S20087
INSPECTOR: ASCHENMEIER, CAMERON DALE / 110584
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual

INSP. START: 2026-Jun-04 06:00 AM PDT
INSP. COMPLETE: 2026-Jun-04 10:15 AM PDT

VEHICLE JUR: British Columbia
PLATE #: VW3865

REGI: 10208477
UNIT/FLEET#:

VIN: 1HTGSSJT6CJ554206
OWNER/LESSEE NAME: MOUNCE CONSTRUCTION LTD.
MOUNCE CONSTRUCTION LTD
PO BOX 814 STN MAIN
Salmon Arm, British Columbia
V1E4N9, Canada

LICENCED GVW(kg): 43000
VEHICLE YEAR: 2012
MAKE: INTERNATNA
MODEL:

BODY STYLE: Dump Truck
ODOMETER: 368448 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) REPLACE 1L CLEISS PIN
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) REPAIRED WIRING TO REAR MARKER LIGHTS
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Repaired (same day) ADJUSTED #1L & #1R WHEEL BEARRINGS
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24L	Automatic	44.5	47.6
2	Clamp	30L	Automatic	50.8	44.5
3	Clamp	30L	Automatic	47.6	50.8

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
10			9	✓
12	12	11	10	
17	17	17	16	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	85	90
2	90	90
3	95	55

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	13	12
Lining (Shoe)	12	12
Lining (Shoe)	12	16

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Road Tester:
Inspector: ASCHENMEIER, CAMERON DALE Signature:

This Inspection Report was submitted to CVSE on 2026-Jun-04 10:16 AMPDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE0014

6/4/2026 10:16:33 AM PDT