



Commercial Vehicle Inspection Report

Decal Number: GN57327
Decal Expiry Date: 2026-Oct-31
Inspection Number: 21751717

Inspection Result:
PASS

FACILITY: 358671 BC LTD / S14170 INSP. TYPE: Complete INSP. START: 2026-Apr-29 05:00 AM PDT
INSPECTOR: LALLY, PALVINDER / 300081 INSP. CLASS: Class 2 - Heavy Vehicle with LGVW INSP. COMPLETE: 2026-Apr-29 06:45 AM PDT
WORK ORDER #: INSP. REASON: Semi-annual

VEHICLE JUR: British Columbia REGI: 01319115 VIN: 4V4LC9KK47N455460
PLATE #: 97655P UNIT/FLEET#: 372 OWNER/LESSEE NAME: RIGHT-LINK TRANSPORT LTD.,
LICENCED GVW(kg): 47000 BODY STYLE: Truck Tractor ADDRESS: 34208 AMBLEWOOD PL
VEHICLE YEAR: 2007 ODOMETER: 1240673 KM Abbotsford, British Columbia
MAKE: VOLVO HUB ODOMETER: V2S 7N2, Canada
MODEL: BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	20	Automatic	32	32
2	Clamp	30	Automatic	34	34
3	Clamp	30	Automatic	34	34

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
13			13	✓
14	14	14	14	
14	14	14	14	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	70	70
2	75	75
3	25	70

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	15	15
Lining (Shoe)	15	15
Lining (Shoe)	21	15

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Inspector: LALLY, PALVINDER

Signature: 

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Apr-29 06:56 AM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVP at the Commercial Vehicle Safety Enforcement

CVSE0014

4/29/2026 6:56:39 AM PDT