



Commercial Vehicle Inspection Report

Decal Number: GN06982
Decal Expiry Date: 2027-Apr-30
Inspection Number: 21742393

Inspection Result:
PASS

K08-4

FACILITY: WOZ MECHANICAL LTD. / S6256 INSP. TYPE: Re-inspection INSP. START: 2026-Apr-22 08:00 AM MDT
INSPECTOR: MAGWOOD, KEVIN WILLIAM / 114950 INSP. CLASS: Class 3 - Trailer and Semi-Trailer INSP. COMPLETE: 2026-Apr-22 08:15 AM MDT
WORK ORDER #: INSP. REASON: Annual
ORIGINAL INSP. #: 21740062

VEHICLE JUR: British Columbia REGI: 11815339 VIN: 5FTDA2239C1038381
PLATE #: 47152L UNIT/FLEET#: OWNER/LESSEE NAME: POOR-BOY HOLDINGS, LTD
LICENCED GVW(kg): 999999 BODY STYLE: Lowbed Trailer ADDRESS: 4021 523RD AVE S
VEHICLE YEAR: 2012 ODOMETER: Cranbrook, British Columbia
MAKE: FELLING HUB ODOMETER: V1C7A3, Canada
MODEL: XF110 BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed with Caution #1 RH INNER TIRE WEAR
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	36	36	17	17	7	14	
2	Clamp	30	Automatic	34	35	8	8	14	14	
3	Clamp	30	Automatic	36	36	10	8	8	15	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	70	55
2	65	70
3	35	80

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	14	15
Lining (Shoe)	14	14
Lining (Shoe)	19	13

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: MAGWOOD, KEVIN WILLIAM

Road Test Date: 
Signature: Road Tester:

This Inspection Report was submitted to CVSE on 2026-Apr-22 08:52 AM MDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVP at the Commercial Vehicle Safety Enforcement

CVSE0014

4/22/2026 8:52:36 AM MDT