



Commercial Vehicle Inspection Report

Decal Number: GP93331
Decal Expiry Date: 2027-Mar-31
Inspection Number: 21934729

Inspection Result:

PASS

FACILITY: WOZ MECHANICAL LTD. / S6256 INSP. TYPE: Complete INSP. START: 2026-Sep-28 10:00 AM MDT
INSPECTOR: MAGWOOD, KEVIN WILLIAM / 114950 INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more INSP. COMPLETE: 2026-Sep-28 11:00 AM MDT
WORK ORDER #: INSP. REASON: Semi-annual
VEHICLE JUR: British Columbia REGI: 10426718 VIN: 1FUJGNBG5CDBJ0347
PLATE #: XY6796 UNIT/FLEET#: OWNER/LESSEE NAME: POOR-BOY HOLDINGS, LTD
LICENCED GVW(kg): 63500 BODY STYLE: Truck Tractor ADDRESS: 4021 53RD ST S
VEHICLE YEAR: 2012 ODOMETER: 593175 KM Cranbrook, British Columbia
MAKE: FREIGHTLIN HUB ODOMETER: V1C7A3, Canada
MODEL: BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	20	Automatic	30	30	18			18	✓
2	Clamp	30L	Automatic	38	37	17	17	18	19	
3	Clamp	30L	Automatic	36	36	16	15	15	17	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right	Brake Lining/Pad (mm)	Left	Right	Rotor Thickness or Drum Inside Diameter (mm)	Left	Right
1	50	60	Lining/Pad	16	15	Drum		
2	70	60	Lining (Shoe)	14	17	Drum		
3	35	35	Lining (Shoe)	19	19	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Road Tester:
Inspector: MAGWOOD, KEVIN WILLIAM Signature:

This Inspection Report was submitted to CVSE on 2026-Sep-28 01:11 PM MDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVF at the Commercial Vehicle Safety Enforcement.

CVSED014

9/28/2026 1:11:30 PM MDT